July 5, 2019

Mr. Alex Baylor, Environmental Specialist via email: alex.baylor@pgcps.org
Environmental Safety Office
Prince Georges County Public Schools
Division of Supporting Services / Building Services
13306 Old Marlboro Pike
Upper Marlboro, MD 20772

RE: Indoor Air Quality (IAQ) and Mold Assessment Services
Benjamin Stoddert Middle School
2501 Olson Street, Temple Hills, MD 20748
Tidewater Project No.: 5419-020

Dear Mr. Baylor:

Tidewater, Inc. (Tidewater) is pleased to present this Indoor Air Quality (IAQ) and Mold Assessment Report describing the results of the IAQ assessment and mold survey conducted by Tidewater at Benjamin Stoddert Middle School located at 2501 Olson Street, Temple Hills, Maryland. The IAQ and Mold survey was conducted on May 31, 2019, by Tidewater's Project Manager and Certified Industrial Hygienist, Mr. Skanda Abeyesekere MS, CIH, CSP, CHMM.

The scope of work for the IAQ assessment and mold survey included:

- Visual inspections of the following areas of the school: Library, Gymnasium, Music Instrument Room, Multipurpose Room, Classroom 110, Classroom 121, 2nd Floor - Classroom 224, 2nd Floor - Guidance Room 227, 3rd Floor – Classroom 326 and 3rd Floor – Classroom 310 of Benjamin Stoddert Middle School for evidence of potential indoor air quality problems (including suspect microbial growth, water damage, chemical use/storage, drain traps, sources of allergens/contaminants, etc.) that may contribute to indoor air quality problems.
- Comfort parameter air testing at the above areas utilizing a direct-reading IAQ monitor for temperature (T), relative humidity (RH), carbon monoxide (CO), and carbon dioxide (CO_2.) Measurements were taken for comparison with guidelines established by the American Society of Heating, Refrigerating and Air-Conditioning Engineers (ASHRAE) Standard 62.1–2016, Ventilation for Acceptable Indoor Air Quality, and The United States Environmental Protection Agency (US EPA) National Ambient Air Quality Standards (NAAQS.)
- Measurement of particulate matter less than 10 microns (PM10) concentrations utilizing a direct-reading instrument at the above areas for comparison with guidelines established by the United States Environmental Protection Agency (US EPA.)
- Measurement of Total Volatile Organic Compounds (TVOCs) concentrations utilizing a direct-reading instrument at the above areas for comparison with relevant guidelines.
- Air sampling for total airborne fungal spore concentrations at the above areas using Allergenco-D cassettes affixed to a Buck BioAire™ Model B520 Bioaerosol Sampling Pump.

Visual Observations

Tidewater's assessment included a visual inspection of selected areas of the school including the Library, Gymnasium, Music Instrument Room, Multipurpose Room, Classroom 110, Classroom 121, 2nd Floor - Classroom 224, 2nd Floor - Guidance Room 227, 3rd Floor – Classroom 326 and 3rd Floor – Classroom 310 of Benjamin Stoddert Middle School. The results of Tidewater's visual inspection are as follows:

Library

The Library was vacant at the time of the inspection. Two (2) wall-mounted air conditioning units were in operation at the time of the inspection. General housekeeping within the Library appeared to be satisfactory. No signs of suspect mold growth or water-intrusion problems were observed in the Library. A strong mildew odor was detected in the Library upon entry.

Gymnasium

Gymnasium was vacant at the time of the inspection. Air diffusers located on the ceiling appeared to be clean. Window-mounted air conditioning units were in operation at the time of the inspection. No signs of suspect mold growth or water intrusion problems were observed within the Gymnasium. Tidewater did not detect any unusual odors in the Gymnasium.

Music Instrument Room (Room 151)

Room 151 had three (3) occupants at the time of the inspection. The air conditioning unit was in operation at the time of the inspection. General housekeeping within the classroom appeared to be deficient. Multiple water-stained ceiling tiles were also observed in the Room 151. Furthermore, the supply air grills located on the ceiling appeared to contain suspect mold formations. No unusual odors were detected.

Multipurpose Room (Room 156)

Multipurpose Room 156 had over 50 students at the time of the inspection. Air diffusers located on the ceiling appeared to be clean. Window-mounted air conditioning units were in operation at the time of the inspection. Multiple water-stained ceiling tiles were also observed in the multipurpose room. Tidewater did not detect any unusual odors in the multi-purpose room.

Classroom 110

Classroom 110 was vacant at the time of the inspection. One (1) wall-mounted fan coil unit was in operation at the time of the inspection. General housekeeping within the classroom appeared to be satisfactory. The supply air grills located on the ceiling appeared to be clean. Ceiling tiles with minor water stains were observed in the classroom. No unusual odors were detected.

Classroom 121

Classroom 121 was vacant at the time of the inspection. One (1) wall-mounted fan coil unit was in operation at the time of the inspection. General housekeeping within the classroom appeared to be satisfactory. The supply air grills located on the ceiling appeared to be clean. Ceiling tiles with minor water stains were observed in the classroom. No unusual odors were detected.

2nd Floor - Classroom 224

Classroom 224 had over 20 students at the time of the inspection. One (1) wall-mounted fan coil unit was in operation at the time of the inspection. General housekeeping within the

classroom appeared to be satisfactory. The supply air grills located on the ceiling appeared to be clean. No unusual odors were detected.

2nd Floor - Guidance Room (Room 227)

Guidance Room (Room 227) was vacant at the time of the inspection. One (1) wall-mounted fan coil unit was in operation at the time of the inspection. General housekeeping within the Guidance room appeared to be satisfactory. The supply air grills located on the ceiling appeared to be clean. No unusual odors were detected.

3rd Floor – Classroom 326

Classroom 326 was vacant at the time of the inspection. One (1) wall-mounted fan coil unit was in operation at the time of the inspection. General housekeeping within the classroom appeared to be satisfactory. The supply air grills located on the ceiling appeared to be clean. No unusual odors were detected.

3rd Floor – Classroom 310

Classroom 310 was vacant at the time of the inspection. One (1) wall-mounted fan coil unit was in operation at the time of the inspection. General housekeeping within the classroom appeared to be satisfactory. The supply air grills located on the ceiling appeared to be clean. No unusual odors were detected.

Comfort Parameter Air Testing

During the assessment, Tidewater recorded temperature, relative humidity, carbon dioxide (CO_2), and carbon monoxide (CO) measurements in the above-mentioned locations of Benjamin Stoddert Middle School using a TSI Q-Track Air Quality Meter (Model Number TSI Q-Track 7565, Serial Number 7565x0931002, Calibration Date: April 18, 2019.) Measurements were taken after allowing the instrument to become acclimated to the ambient temperature and relative humidity for approximately five (5) minutes. Measurements were taken over a 5-minute time period at each designated location and the average concentration was recorded. Samples were obtained for comparison with guidelines established by the American Society for Heating Refrigeration and Air Conditioning (ASHRAE) Standard 62.1 – 2016, Ventilation for Acceptable Indoor Air Quality. A background sample was obtained in front of the main entrance to the school building for comparison to the interior readings. The results of the IAQ comfort parameter monitoring are provided in Table 1, in **Attachment A**.

According to the American Society for Heating, Refrigerating and Air Conditioning Engineers (ASHRAE) Standard 62.1 – 2016, the temperature range in summer months should be maintained between 73.0°F and 79.0°F for maximum occupant comfort. The ASHRAE guideline for temperature for winter months is between 68.0°F and 74.5°F. The indoor temperature levels recorded in the assessed areas ranged between 74.6°F and 78.7°F. The background temperature outside the building was 79.5°F. The temperature levels recorded in all areas were within the temperature guideline recommended in ASHRAE Standard 62.1 – 2016 for summer months.

Per the same guideline, a maximum relative humidity level of 65.0% is recommended to reduce the likelihood of condensation on cold surfaces. Relative humidity levels recorded in the assessed areas ranged between 59.0% and 65.9%. The background relative humidity level outside the building was 60.1%. The relative humidity level in the Library, Multipurpose Room and Classroom 121 were marginally above the ASHRAE recommended maximum relative humidity guideline of 65.0%.

ASHRAE Standard 62.1 – 2016 recommends that indoor CO_2 concentrations not exceed 700 ppm above the outdoor background CO_2 level. The CO_2 levels recorded in the assessed areas ranged between 450 ppm to 1,149 ppm. The background CO_2 level outside the building was 420 ppm. The CO_2 levels on the 2nd floor Classroom 224 exceeded 700 ppm above the outdoor background CO_2 level of 420 ppm indicating inadequate air flow into this office space. These areas are highlighted in Table 1, in **Attachment A**.

The CO concentrations recorded in all of the assessed areas were below the maximum guideline of 9 ppm recommended by the Indoor Air Quality Association (IAQA) for CO in occupied indoor environments.

Particulate Matter Less than 10 Microns (PM 10)

Tidewater conducted air sampling for respirable dust particulates using a TSI® DUST TRAK DRX™ Aerosol Monitor (Serial Number 8534170101, Calibrated Date: March 1, 2019.) The TSI® DUST TRAK DRX™ Aerosol Monitor was equipped with a PM10 (10 µm) respirable impactor. Measurements were taken after allowing the device to become acclimated to the ambient temperature and relative humidity for five (5) minutes. Measurements were taken over a 5-minute time period at each designated location and the average concentration was recorded. Samples were taken for comparison with guidelines established by the EPA NAAQS. Tidewater also obtained a background sample from outside the main entrance of the school building for comparison to the interior readings. The results of the particulate matter sampling are provided in Table 2, in **Attachment A**.

Based on the EPA National Ambient Air Quality Standard (NAAQS) for Particulate Matter, Final Rule (January 15, 2013), the 24-hour primary and secondary exposure standard for particulate matter less than 10 microns (PM10) is 150.0 micrograms per cubic meter of air (µg/m^3) or 0.150 milligrams per cubic meter of air (mg/m^3.) The results of the PM10 analysis indicate that the average PM10 dust concentration recorded in all of the assessed areas ranged between 0.012 mg/m^3 and 0.027 mg/m^3. The average PM10 dust concentration in the background sample obtained in front of the main entrance was 0.023 mg/m^3.

The results of the PM10 monitoring indicate that the PM10 dust concentration in all areas assessed were below the EPA 24-hour primary and secondary NAAQS of 0.150 mg/m^3.

Total Volatile Organic Compound (TVOC) Air Testing

Tidewater obtained direct read measurements for Total Volatile Organic Compounds (TVOCs) using a Mini-RAE 2000 Hand Held VOC meter (Model Number MINIRAE 2000, Serial Number 110-010833, Calibration Date April 9, 2019.) Measurements were taken after allowing the device to become acclimated to the ambient temperature and relative humidity for five (5) minutes. Measurements were taken over a 5-minute time period at each sampling location and the average concentration was recorded for comparison with threshold limits recommended for typical indoor occupied environments.

A background sample was also obtained outdoors in front of the main entrance of the school building for comparison to the indoor readings. The results of the particulate matter sampling are provided in Table 3, in **Attachment A**.

There are no OSHA published guidelines for TVOCs. However, in general, the indoor air quality TVOC threshold for typical indoor occupied environments should not exceed 1,000 ppb (1.0 ppm) isobutylene units. The TVOC concentrations recorded in all of the assessed areas were below the recommended threshold level of 1.0 ppm.

Spore Trap Bioaerosol Sampling

On May 31, 2019, Tidewater collected a total of eleven (11) spore trap air samples using Allergenco-D cassettes to characterize potential airborne fungal spores within select areas of Benjamin Stoddert Middle School. A background sample was also collected outside the main entrance to the school building for comparison purposes.

Tidewater obtained the spore trap samples using Allergenco-D cassettes affixed to a Buck BioAire™ Bioaerosol Sampling Pump (Pump Model Number B520 and Serial Number B153043, Calibration Date: February 6, 2019) calibrated to a flow rate of 15.0 Liters per minute. Each sample was run for a period of five (5) minutes at each sample location to collect a total sample volume of 75.0 liters of air.

Once collected, the samples were transported to EMSL Analytical Laboratory (EMSL) located in Beltsville, Maryland for analysis. The samples were transported following rigorous chain-of-custody guidelines to ensure proper handling and delivery of the samples. EMSL is accredited in the American Industrial Hygiene Association (AIHA) Environmental Microbiology Laboratory Accreditation Program (EMLAP) and is a successful participant in AIHA's Environmental Microbiology Proficiency Analytical Testing (EMPAT) program (Laboratory Number 102891.)

The samples were analyzed via light microscopy at the standardized magnification of 600X. This technique does not allow for the differentiation between *Aspergillus* and *Penicillium* spores because they are morphologically identical. Additionally, the technique does not allow for cultivation, or the identification of spores to the species level, except in a few cases.

There are no universally accepted federal or State of Maryland standards for acceptable airborne concentrations of bioaerosols in an indoor occupational environment. In general, airborne concentrations indoors should be less than that found in the outdoor air, with similar species composition. Indoor spore counts significantly greater than those detected outdoors, or the presence of large numbers of different types of spores indoors that are not found outdoors, may indicate contamination and potential indoor air quality problems.

The total mold spore counts for the interior samples ranged between 8,510 and 31,380 spores per cubic meter (spores/m^3.) The total mold spore concentration in the outdoors (background) sample was 43,340 spores/m^3. The total mold spore concentrations in all interior locations sampled were significantly below the outdoors (background) total mold spore concentration.

Additionally, the individual fungal species concentrations observed in the interior samples were generally consistent with those observed in the background reference sample with no significant concentrations of an individual fungal species identified in the interior samples.

The summary of the results for the spore trap sampling are provided in Table 4 in **Attachment A**. The laboratory analytical results, including speciation and chain of custody forms for the spore trap samples are included in **Attachment B**.

Conclusions

Based on this IAQ and mold assessment survey, Tidewater offers the following conclusions:

- Tidewater's visual inspection did not reveal any evidence of standing water, active water intrusion or suspect mold growth on accessible walls, floors and ceilings in the assessed areas. Water-stained ceiling tiles were observed in Music Instrument Room (Room 151), Multipurpose Room.

- The supply air grills located on the ceiling of the Music Instrument Room (Room 151) appeared to contain dust and suspect mold growth.
- General housekeeping in all areas assessed appeared to be good apart from the Music Instrument Room (Room 151.)
- The CO, PM10, Temperature and TVOC readings recorded within the assessed areas were all within industry standards and guidelines.
- The relative humidity level in the Library, Multipurpose Room and Classroom 121 were marginally above the ASHRAE recommended maximum relative humidity guideline of 65.0%.
- The CO_2 levels on the 2nd floor Classroom 224 exceeded 700 ppm above the outdoor background CO_2 level of 420 ppm and indicates inadequate air flow into this office space.
- The mold spore concentrations in all interior locations sampled were significantly below the outdoors (background) total mold spore concentration. Additionally, the individual fungal species concentrations observed in the interior samples were generally consistent with those observed in the background reference samples with no significant concentrations of an individual fungal species identified in the interior samples.

Recommendations

Based on the results of the assessment, Tidewater offers the following recommendations:

- Abate the water-stained ceiling tiles in the Music Instrument Room (Room 151) and Multipurpose Room. Ensure that the perimeters of the ceiling grids are cleaned with a 10% bleach solution to mitigate exiting fungal spores prior to installing new ceiling tiles.
- Clean air supply grills located on the ceiling of the Music Instrument Room (Room 151) with a 10% bleach solution to mitigate observed dust and suspect mold growth.
- Ensure that all cleaning activities are conducted after hours when the classrooms are vacant to minimize exposure to occupants.
- Maintain good housekeeping practices in all common areas and classrooms. All common area and classroom floors should be broom cleaned at the end of each day. Furthermore, all horizontal surfaces including desktops, furniture, window sills and suspended light fixtures should be cleaned on a routine basis to prevent the accumulations of dust.
- Ensure HVAC System supplying is properly balanced per design requirements and current use/occupancy in order to ensure adequate ventilation throughout the classrooms.
- Ensure the ventilation systems are turned on in all classrooms and are operating at all times when the classrooms are occupied to provide sufficient air flow and ventilation to the classrooms**.**
- Install dehumidifiers or adjust the HVAC systems serving the Library, Multipurpose Room and Classroom 121 in order to achieve a relative humidity level below 65.0% per ASHRAE Standard 62.1-2016 in order to lower the probability of mold formations.

- Increase the air exchange rate on the 2nd floor Classroom 224 in order improve the air circulation within the classroom.
- Further investigation is warranted in the Library to address the strong mildew odor. This should include the Library area as well as the HVAC system supplying this area.

Qualifications

Tidewater has endeavored to investigate existing conditions in representative areas of Benjamin Stoddert Middle School located at 2501 Olson Street, Temple Hills, Maryland as they pertain to indoor air quality. Our conclusions and recommendations are based on the observations made on the day of our assessment, laboratory data from the time of the assessment, and information provided by both our Client and the area occupants. Actual conditions vary from day to day throughout the year.

Tidewater appreciates the opportunity to provide Industrial Hygiene consulting services for Prince Georges County Public Schools. Please contact us should any questions arise concerning this report or if we may be of further assistance.

Sincerely,
Tidewater, Inc.

Skanda Abeyesekere, MS, CIH, CSP, CHMM
Project Manager

Jonathan N. Schatz, MS
Manager, IH Services

SA/JNS

Attachments: **Attachment A – Summary of Comfort Parameters, Total (Nuisance) Dust, TVOC and Non-Viable Spore Trap Sampling**
Attachment B – Laboratory Reports for Non-Viable Spore Trap Sampling
Attachment C – Calibration Certificates
Attachment D – Qualifications
Attachment E – Floor Plan with Sampling Locations

Attachment A

Summary of Comfort Parameters, Total (Nuisance) Dust, TVOC and Non-Viable Spore Trap Sampling

Table 1: Indoor Air Quality Comfort Parameters Benjamin Stoddert Middle School				
Location	**Temperature (°F)**	**Relative Humidity (%)**	**Carbon Dioxide (ppm)**	**Carbon Monoxide (ppm)**
May 31, 2019				
Library	75.3	**65.9**	458	0.1
Gymnasium	77.1	65.0	459	0.0
Music Instrument Room	75.8	64.9	450	0.0
Multi-Purpose Room	76.1	**65.3**	603	0.1
Classroom 110	74.6	62.8	520	0.0
Classroom 121	76.6	**65.4**	780	0.0
2nd Floor - Classroom 224	78.1	62.9	**1,149**	0.0
2nd Floor - Guidance Room 227	76.9	59.7	573	0.1
3rd Floor - Classroom 326	78.7	59.0	545	0.0
3rd Floor - Classroom 310	76.3	60.6	641	0.0
Background	79.5	60.1	420	0.0

- Numbers highlighted in red indicates locations in which temperature, carbon dioxide or relative humidity levels were either above or below the guidelines recommended by the American Society for Heating Refrigeration and Air Conditioning (ASHRAE) Standard 62.1 – 2016.

Table 2: Particulate Matter Less than 10 Microns (PM10) Benjamin Stoddert Middle School	
Location	**Particulate Matter (PM10)** **Concentration (mg/m^3)**
May 31, 2019	
Library	0.012
Gymnasium	0.015
Music Instrument Room	0.014
Multi-Purpose Room	0.016
Classroom 110	0.021
Classroom 121	0.027
2nd Floor - Classroom 224	0.024
2nd Floor - Guidance Room 227	0.022
3rd Floor - Classroom 326	0.018
3rd Floor - Classroom 310	0.018
Background (Outdoors)	0.023

- Highlighted areas indicates locations where the PM0 particulate concentration exceeded the EPA 24-hour primary and secondary NAAQS of 0.150 mg/m^3.

Table 3: Total Volatile Organic Compounds (TVOCs) Benjamin Stoddert Middle School	
Location	**Concentration (ppm)**
May 31, 2019	
Library	0.1
Gymnasium	0.1
Music Instrument Room	0.0
Multi-Purpose Room	0.0
Classroom 110	0.0
Classroom 121	0.0
2nd Floor - Classroom 224	0.0
2nd Floor - Guidance Room 227	0.0
3rd Floor - Classroom 326	0.0
3rd Floor - Classroom 310	0.0
Background (Outdoors)	0.1

Table 4: Spore Trap Sampling Results Benjamin Stoddert Middle School			
May 31, 2019			
Sample Number	**Sample Location**	**Sample Volume (L)**	**Total Fungi Concentration (Counts/m^3)**
BSMS-1	Library	75.0	13,840
BSMS-2	Gymnasium	75.0	31,380
BSMS-3	Music Instrument Room	75.0	25,050
BSMS-4	Multi-Purpose Room	75.0	13,830
BSMS-5	Classroom 110	75.0	19,270
BSMS-6	Classroom 121	75.0	23,750
BSMS-7	2nd Floor - Classroom 224	75.0	11,990
BSMS-8	2nd Floor - Guidance Room 227	75.0	8,510
BSMS-9	3rd Floor - Classroom 326	75.0	12,300
BSMS-10	3rd Floor - Classroom 310	75.0	None Detected
BG-1	Background (Outdoors)	75.0	43,340

- Highlighted Area indicates location where the concentrations of the indoor sample exceeded the level detected in the background sample.

Attachment B

Laboratory Reports for Non-Viable Spore Trap Mold Sampling

EMSL Analytical, Inc.

528 Mineola Avenue Carle Place, NY 11514
Phone/Fax: (516) 997-7251 / (516) 997-7528
http://www.EMSL.com / carleplacelab@emsl.com

Order ID: 061910762
Customer ID: TIDE50
Customer PO:
Project ID:

Attn: Skanda Abeyeskere
Tidewater, Inc.
6625 Selnick Drive
Suite A
Elkridge, MD 21075

Phone: (410) 540-8700
Fax: (410) 997-8713
Collected: 05/31/2019
Received: 06/03/2019
Analyzed: 06/04/2019

Proj: Benjamin Stohard MS 5419-020

Test Report: Allergenco-D(™) Analysis of Fungal Spores & Particulates by Optical Microscopy (Methods MICRO-SOP-201, ASTM D7391)

Lab Sample Number:	061910762-0001			061910762-0002			061910762-0003		
Client Sample ID:	BSMS-1			BSMS-2			BSMS-3		
Volume (L):	75			75			75		
Sample Location:	Library			Gymnasium			Music Instrument Room		
Spore Types	Raw Count	Count/m³	% of Total	Raw Count	Count/m³	% of Total	Raw Count	Count/m³	% of Total
Alternaria (Ulocladium)	-	-	-	-	-	-	-	-	-
Ascospores	4	200	1.4	42	1800	5.7	15	660	2.6
Aspergillus/Penicillium	-	-	-	-	-	-	-	-	-
Basidiospores	311	13600	98.3	677	29500	94	556	24300	97
Bipolaris++	1	40	0.3	-	-	-	-	-	-
Chaetomium	-	-	-	-	-	-	-	-	-
Cladosporium	-	-	-	1	40	0.1	2	90	0.4
Curvularia	-	-	-	-	-	-	-	-	-
Epicoccum	-	-	-	-	-	-	-	-	-
Fusarium	-	-	-	-	-	-	-	-	-
Ganoderma	-	-	-	-	-	-	-	-	-
Myxomycetes++	-	-	-	-	-	-	-	-	-
Pithomyces++	-	-	-	-	-	-	-	-	-
Rust	-	-	-	-	-	-	-	-	-
Scopulariopsis/Microascus	-	-	-	-	-	-	-	-	-
Stachybotrys/Memnoniella	-	-	-	-	-	-	-	-	-
Unidentifiable Spores	-	-	-	-	-	-	-	-	-
Zygomycetes	-	-	-	-	-	-	-	-	-
Cercospora++	-	-	-	-	-	-	-	-	-
Polythrincium	-	-	-	1	40	0.1	-	-	-
Torula-like	-	-	-	-	-	-	-	-	-
Total Fungi	**316**	**13840**	**100**	**721**	**31380**	**100**	**573**	**25050**	**100**
Hyphal Fragment	1*	10*	-	-	-	-	-	-	-
Insect Fragment	-	-	-	-	-	-	-	-	-
Pollen	-	-	-	-	-	-	1	40	-
Analyt. Sensitivity 600x	-	44	-	-	44	-	-	44	-
Analyt. Sensitivity 300x	-	13*	-	-	13*	-	-	13*	-
Skin Fragments (1-4)	-	2	-	-	1	-	-	2	-
Fibrous Particulate (1-4)	-	1	-	-	1	-	-	1	-
Background (1-5)	-	2	-	-	2	-	-	2	-

++ Includes other spores with similar morphology; see EMSL's fungal glossary for each specific category.

No discernable field blank was submitted with this group of samples.



Jeffrey Lau, Microbiology Laboratory Manager
or Other Approved Signatory

Initial report from: 06/05/2019 12:50:39

For Information on the fungi listed in this report please visit the Resources section at www.emsl.com

EMSL Analytical, Inc.

528 Mineola Avenue Carle Place, NY 11514
Phone/Fax: (516) 997-7251 / (516) 997-7528
http://www.EMSL.com / carleplacelab@emsl.com

Order ID: 061910762
Customer ID: TIDE50
Customer PO:
Project ID:

Attn: Skanda Abeyeskere
Tidewater, Inc.
6625 Selnick Drive
Suite A
Elkridge, MD 21075

Phone: (410) 540-8700
Fax: (410) 997-8713
Collected: 05/31/2019
Received: 06/03/2019
Analyzed: 06/04/2019

Proj: Benjamin Stohard MS 5419-020

Test Report: Allergenco-D(™) Analysis of Fungal Spores & Particulates by Optical Microscopy (Methods MICRO-SOP-201, ASTM D7391)

Lab Sample Number:	061910762-0004			061910762-0005			061910762-0006		
Client Sample ID:	BSMS-4			BSMS-5			BSMS-6		
Volume (L):	75			75			75		
Sample Location:	Multipurpose Rm			Classroom 110			Classroom 121		
Spore Types	Raw Count	Count/m³	% of Total	Raw Count	Count/m³	% of Total	Raw Count	Count/m³	% of Total
Alternaria (Ulocladium)	-	-	-	-	-	-	-	-	-
Ascospores	14	610	4.4	19	830	4.3	8	300	1.3
Aspergillus/Penicillium	-	-	-	-	-	-	1	40	0.2
Basidiospores	300	13100	94.7	418	18200	94.4	532	23200	97.7
Bipolaris++	-	-	-	-	-	-	-	-	-
Chaetomium	-	-	-	-	-	-	-	-	-
Cladosporium	1	40	0.3	4	200	1	5	200	0.8
Curvularia	-	-	-	-	-	-	-	-	-
Epicoccum	1	40	0.3	1	40	0.2	-	-	-
Fusarium	-	-	-	-	-	-	-	-	-
Ganoderma	-	-	-	-	-	-	-	-	-
Myxomycetes++	1	40	0.3	-	-	-	1*	10*	0
Pithomyces++	-	-	-	-	-	-	-	-	-
Rust	-	-	-	-	-	-	-	-	-
Scopulariopsis/Microascus	-	-	-	-	-	-	-	-	-
Stachybotrys/Memnoniella	-	-	-	-	-	-	-	-	-
Unidentifiable Spores	-	-	-	-	-	-	-	-	-
Zygomycetes	-	-	-	-	-	-	-	-	-
Cercospora++	-	-	-	-	-	-	-	-	-
Polythrincium	-	-	-	-	-	-	-	-	-
Torula-like	-	-	-	-	-	-	-	-	-
Total Fungi	**317**	**13830**	**100**	**442**	**19270**	**100**	**547**	**23750**	**100**
Hyphal Fragment	-	-	-	1	40	-	-	-	-
Insect Fragment	-	-	-	-	-	-	-	-	-
Pollen	-	-	-	-	-	-	-	-	-
Analyt. Sensitivity 600x	-	44	-	-	44	-	-	44	-
Analyt. Sensitivity 300x	-	13*	-	-	13*	-	-	13*	-
Skin Fragments (1-4)	-	2	-	-	2	-	-	3	-
Fibrous Particulate (1-4)	-	1	-	-	2	-	-	2	-
Background (1-5)	-	2	-	-	3	-	-	3	-

++ Includes other spores with similar morphology; see EMSL's fungal glossary for each specific category.

No discernable field blank was submitted with this group of samples.

Jeffrey Lau, Microbiology Laboratory Manager
or Other Approved Signatory

Samples received in good condition unless otherwise noted. High levels of background particulate can obscure spores and other particulates, leading to underestimation. Background levels of 5 indicate an overloading of background particulates, prohibiting accurate detection and quantification. Present = Spores detected on overloaded samples. Results are not blank corrected unless otherwise noted. The detection limit is equal to one fungal spore, structure, pollen, fiber particle or insect fragment. "*" Denotes particles found at 300X. "-" Denotes not detected. Due to method stopping rules, raw counts in excess of 100 are extrapolated based on the percentage analyzed. EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. The report reflects the samples as received. When the information supplied by the customer can affect the validity of the result, it will be noted on the report.
Samples analyzed by EMSL Analytical, Inc. Carle Place, NY

Initial report from: 06/05/2019 12:50:39

For Information on the fungi listed in this report please visit the Resources section at www.emsl.com

EMSL Analytical, Inc.
528 Mineola Avenue Carle Place, NY 11514
Phone/Fax: (516) 997-7251 / (516) 997-7528
http://www.EMSL.com / carleplacelab@emsl.com

Order ID: 061910762
Customer ID: TIDE50
Customer PO:
Project ID:

Attn: Skanda Abeyeskere
Tidewater, Inc.
6625 Selnick Drive
Suite A
Elkridge, MD 21075

Phone: (410) 540-8700
Fax: (410) 997-8713
Collected: 05/31/2019
Received: 06/03/2019
Analyzed: 06/04/2019

Proj: Benjamin Stohard MS 5419-020

Test Report: Allergenco-D(™) Analysis of Fungal Spores & Particulates by Optical Microscopy (Methods MICRO-SOP-201, ASTM D7391)

Lab Sample Number:	061910762-0007			061910762-0008			061910762-0009		
Client Sample ID:	BSMS-7			BSMS-8			BSMS-9		
Volume (L):	75			75			75		
Sample Location:	Classroom 224			Guidance Room 277			3rd Fl. Room 326		
Spore Types	Raw Count	Count/m³	% of Total	Raw Count	Count/m³	% of Total	Raw Count	Count/m³	% of Total
Alternaria (Ulocladium)	-	-	-	-	-	-	-	-	-
Ascospores	14	610	5.1	12	520	6.1	4	200	1.6
Aspergillus/Penicillium	-	-	-	-	-	-	-	-	-
Basidiospores	249	10900	90.9	183	7990	93.9	275	12000	97.6
Bipolaris++	-	-	-	-	-	-	-	-	-
Chaetomium	-	-	-	-	-	-	-	-	-
Cladosporium	11	480	4	-	-	-	3	100	0.8
Curvularia	-	-	-	-	-	-	-	-	-
Epicoccum	-	-	-	-	-	-	-	-	-
Fusarium	-	-	-	-	-	-	-	-	-
Ganoderma	-	-	-	-	-	-	-	-	-
Myxomycetes++	-	-	-	-	-	-	-	-	-
Pithomyces++	-	-	-	-	-	-	-	-	-
Rust	-	-	-	-	-	-	-	-	-
Scopulariopsis/Microascus	-	-	-	-	-	-	-	-	-
Stachybotrys/Memnoniella	-	-	-	-	-	-	-	-	-
Unidentifiable Spores	-	-	-	-	-	-	-	-	-
Zygomycetes	-	-	-	-	-	-	-	-	-
Cercospora++	-	-	-	-	-	-	-	-	-
Polythrincium	-	-	-	-	-	-	-	-	-
Torula-like	-	-	-	-	-	-	-	-	-
Total Fungi	**274**	**11990**	**100**	**195**	**8510**	**100**	**282**	**12300**	**100**
Hyphal Fragment	-	-	-	2*	30*	-	-	-	-
Insect Fragment	-	-	-	-	-	-	-	-	-
Pollen	1*	10*	-	-	-	-	-	-	-
Analyt. Sensitivity 600x	-	44	-	-	44	-	-	44	-
Analyt. Sensitivity 300x	-	13*	-	-	13*	-	-	13*	-
Skin Fragments (1-4)	-	3	-	-	2	-	-	2	-
Fibrous Particulate (1-4)	-	2	-	-	2	-	-	2	-
Background (1-5)	-	3	-	-	3	-	-	2	-

++ Includes other spores with similar morphology; see EMSL's fungal glossary for each specific category.

No discernable field blank was submitted with this group of samples.

Jeffrey Lau, Microbiology Laboratory Manager
or Other Approved Signatory

Samples received in good condition unless otherwise noted. High levels of background particulate can obscure spores and other particulates, leading to underestimation. Background levels of 5 indicate an overloading of background particulates, prohibiting accurate detection and quantification. Present = Spores detected on overloaded samples. Results are not blank corrected unless otherwise noted. The detection limit is equal to one fungal spore, structure, pollen, fiber particle or insect fragment. "*" Denotes particles found at 300X. "-" Denotes not detected. Due to method stopping rules, raw counts in excess of 100 are extrapolated based on the percentage analyzed. EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. The report reflects the samples as received. When the information supplied by the customer can affect the validity of the result, it will be noted on the report.
Samples analyzed by EMSL Analytical, Inc. Carle Place, NY

Initial report from: 06/05/2019 12:50:39

For Information on the fungi listed in this report please visit the Resources section at www.emsl.com

EMSL Analytical, Inc.
528 Mineola Avenue Carle Place, NY 11514
Phone/Fax: (516) 997-7251 / (516) 997-7528
http://www.EMSL.com / carleplacelab@emsl.com

Order ID: 061910762
Customer ID: TIDE50
Customer PO:
Project ID:

Attn: Skanda Abeyeskere
Tidewater, Inc.
6625 Selnick Drive
Suite A
Elkridge, MD 21075

Phone: (410) 540-8700
Fax: (410) 997-8713
Collected: 05/31/2019
Received: 06/03/2019
Analyzed: 06/04/2019

Proj: Benjamin Stohard MS 5419-020

Test Report: Allergenco-D(™) Analysis of Fungal Spores & Particulates by Optical Microscopy (Methods MICRO-SOP-201, ASTM D7391)

Lab Sample Number:	061910762-0010			061910762-0011		
Client Sample ID:	BG-1			BSMS-10		
Volume (L):	75			75		
Sample Location:	Outdoors			3rd Floor		
Spore Types	Raw Count	Count/m³	% of Total	Raw Count	Count/m³	% of Total
Alternaria (Ulocladium)	1*	10*	0	-	-	-
Ascospores	120	5240	12.1	-	-	-
Aspergillus/Penicillium	42	1800	4.2	-	-	-
Basidiospores	792	34600	79.8	-	-	-
Bipolaris++	-	-	-	-	-	-
Chaetomium	-	-	-	-	-	-
Cladosporium	35	1500	3.5	-	-	-
Curvularia	1	40	0.1	-	-	-
Epicoccum	-	-	-	-	-	-
Fusarium	-	-	-	-	-	-
Ganoderma	-	-	-	-	-	-
Myxomycetes++	-	-	-	-	-	-
Pithomyces++	-	-	-	-	-	-
Rust	-	-	-	-	-	-
Scopulariopsis/Microascus	-	-	-	-	-	-
Stachybotrys/Memnoniella	-	-	-	-	-	-
Unidentifiable Spores	-	-	-	-	-	-
Zygomycetes	-	-	-	-	-	-
Cercospora++	1	40	0.1	-	-	-
Polythrincium	3	100	0.2	-	-	-
Torula-like	1*	10*	0	-	-	-
Total Fungi	**996**	**43340**	**100**	-	None Detected	-
Hyphal Fragment	-	-	-	-	-	-
Insect Fragment	-	-	-	-	-	-
Pollen	3*	40*	-	1	40	-
Analyt. Sensitivity 600x	-	44	-	-	44	-
Analyt. Sensitivity 300x	-	13*	-	-	13*	-
Skin Fragments (1-4)	-	1	-	-	1	-
Fibrous Particulate (1-4)	-	1	-	-	1	-
Background (1-5)	-	2	-	-	1	-

++ Includes other spores with similar morphology; see EMSL's fungal glossary for each specific category.

No discernable field blank was submitted with this group of samples.

Jeffrey Lau, Microbiology Laboratory Manager
or Other Approved Signatory

Samples received in good condition unless otherwise noted. High levels of background particulate can obscure spores and other particulates, leading to underestimation. Background levels of 5 indicate an overloading of background particulates, prohibiting accurate detection and quantification. Present = Spores detected on overloaded samples. Results are not blank corrected unless otherwise noted. The detection limit is equal to one fungal spore, structure, pollen, fiber particle or insect fragment. "*" Denotes particles found at 300X. "-" Denotes not detected. Due to method stopping rules, raw counts in excess of 100 are extrapolated based on the percentage analyzed. EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. The report reflects the samples as received. When the information supplied by the customer can affect the validity of the result, it will be noted on the report.
Samples analyzed by EMSL Analytical, Inc. Carle Place, NY

Initial report from: 06/05/2019 12:50:39

For Information on the fungi listed in this report please visit the Resources section at www.emsl.com

OrderID: 061910762

Microbiology Chain of Custody

EMSL Order Number *(Lab Use Only)*:

061910762

PHONE:
FAX:

Company: Tidewater Inc	**EMSL-Bill to:** ☐ Different ☐ Same If Bill to is Different note instructions in Comments**
Street: 6625 Selnick Drive, Suite A	*Third Party Billing requires written authorization from third party*
City: Elkridge **State/Province:** MD	**Zip/Postal Code:** **Country:**
Report To (Name): Skanda Abeyesekere	**Telephone #:**
Email Address: skanda@tideh2o.net	**Fax #:** **Purchase Order:**
Project Name/Number: Benjamin Stoddard MS	**Please Provide Results:** ☐ FAX ☐ E-mail ☐ Mail
U.S. State Samples Taken: Maryland 54/9-020	**Connecticut Samples:** ☐ Commercial ☐ Residential

Turnaround Time (TAT) Options* - Please Check

☐ 3 Hour ☐ 6 Hour ☒ 24 Hour ☐ 48 Hour ☐ 72 Hour ☐ 96 Hour ☐ 1 Week ☒ 2 Week

**Analysis completed in accordance with EMSL's Terms and Conditions located in the Analytical Price Guide. TATs are subject to methodology requirements*

Non Culturable Air Samples (Spore Traps) – Test Codes

• **M001** Air-O-Cell	• **M173** Allegro M2	• **M004** Allergenco	• **M032** Allergenco-D	• **M172** Versa Trap
• **M049** BioSIS	• **M003** Burkard	• **M043** Cyclex	• **M002** Cyclex-d	
• **M030** Micro 5	• **M174** MoldSnap	• **M176** Relle Smart	• **M130** Via-Cell	

Other Microbiology Test Codes

• **M041** Fungal Direct Examination	• **M014** Endotoxin Analysis	• **M029** *Enterococci*
• **M005** Viable Fungi ID and Count	• **M015** Heterotrophic Plate Count	• **M019** Fecal Coliform
• **M006** Viable Fungi ID and Count (Speciation)	• **M180** Real Time Q-PCR-ERMI 36	• **M133** MRSA Analysis
• **M007** Culturable Fungi	• Panel	• **M028** *Cryptococcus neoformans*
• **M008** Culturable Fungi (Speciation)	• **M018** Total Coliform	Detection
• **M009** Gram Stain Culturable Bacteria	(Membrane Filtration)	• **M120** *Histoplasma capsulatum*
• **M010** Bacterial Count and ID – 3 Most	• **M020** Fecal *Streptococcus*	Detection
Prominent	(Membrane Filtration)	• **M033-39** Allergen Testing
• **M011** Bacterial Count and ID – 5 Most	• **M210-215** *Legionella* Detection	• **M044** Group Allergen
Prominent	• **M026** Recreational Water Screen	(Cat, Dog, Cockroach, Dustmites)
• **M013** Sewage Contamination in Buildings	• **M027** Mycotoxin Analysis	• **Other** See Analytical Price Guide

Preservation Method (Water):

Name of Sampler: Skanda Abeyesekere **Signature of Sampler:**

Sample #	Sample Location	Sample Type	Test Code	Volume/Area	Date/Time Collected
Example: A1	Kitchen	Air	M001	75L	1/1/12 4:00 PM
BSMS-1	Library	Air	M032	75	05/31/19
-2	Gymnasium			all	
-3	Music Instrument Room				
-4	Multipurpose Rm.				
-5	Classroom 110				
-6	Classroom 121				
-7	Classroom 224				
-8	Guidance Room 227				
-9	3rd Fl. Room 326				

Client Sample # (s): 1 thru 9 **Total # of Samples:** 14

Relinquished (Client): **Date:** **Time:**

Received (Client): **Date:** 6/3/19 **Time:** 1:45 pm

Comments:

Aliquot released 6/4/19

OrderID: 061910762

Microbiology Chain of Custody

EMSL Order Number (*Lab Use Only*):

061910762

PHONE:
FAX:

Additional Pages of the Chain of Custody are only necessary if needed for additional sample information

Sample #	Sample Location	Sample Type	Test Code	Volume/Area	Date/Time Collected
BG-1	Outdoors	Air	M032	75-0	05/31/2019
BSMS-10	3rd floor	"	"	"	"
8					

****Comments/Special Instructions:**

Angela McDonald 6/4/19

Page 2 of 2 pages

Attachment C

Calibration Certificates

FIELD ENVIRONMENTAL INSTRUMENTS, INC.
www.fieldenvironmental.com

301 Brushton Avenue
Suite A
Pittsburgh PA 15221
800-393-4009 Toll Free
(412) 436-2600 Local
(412) 436-2616 Fax

IAQ Meter Calibration Certificate

	Lot #	Expiration
Cal Standard	18-6508	4/18/2020

Carbon Monoxide Gas	**Reading ppm**	**Acceptable Range**
35 ppm	35.0	(32 - 38)

Carbon Dioxide Gas	**Reading ppm**	**Acceptable Range**
1000 ppm	1008.0	(950 - 1050)

Model	TSI Q-Trak 7565
S/N	7565x0931002
Barcode	u59038x
Order #	398188

Calibrated By: Bryce Spontak

Date of Calibration: 05/16/19

All calibrations performed by FEI conform to manufacturer's specifications. Please report any issues within 24 hours of receiving equipment.
All calibration gas used is traceable to NIST. Additional documentation is available upon request.

TSI P/N 2300157

CERTIFICATE OF CALIBRATION AND TESTING

TSI Incorporated, 500 Cardigan Road, Shoreview, MN 55126 USA
Tel: 1-800-874-2811 1-651-490-2811 Fax: 1-651-490-3824 http://www.tsi.com

Environment Conditions		
Temperature	76.6 (24.8)	°F (°C)
Relative Humidity	24	%RH
Barometric Pressure	29.14 (986.8)	inHg (hPa)

Model	**8534**
Serial Number	**8534170101**

☐ As Left ☐ In Tolerance
☒ As Found ☒ Out of Tolerance

Concentration Linearity Plot



System ID: DTII01-02

FLOW AND PRESSURE VERIFICATION — **SYSTEM DTII01-02**

Parameter	Standard	Measured	Allowable Range	Parameter	Standard	Measured	Allowable Range
Flow lpm	3.0	3.0	2.85 ~ 3.15	Pressure kPa	98.6	98.6	93.71 ~ 103.57

Pump run time: 25 Hours, Pump voltage: 433 Bits

TSI Incorporated does hereby certify that all materials, components, and workmanship used in the manufacture of this equipment are in strict accordance with the applicable specifications agreed upon by TSI and the customer and with all published specifications. All performance and acceptance tests required under this contract were successfully conducted according to required specifications. There is no NIST standard for optical mass measurements. Calibration of this instrument performed by TSI has been done using emery oil and has been nominally adjusted to respirable mass per standard ISO 12103-1, A1 test dust (Arizona dust). Our calibration ratio is greater than 1.2:1

Measurement Variable	System ID	Last Cal.	Cal. Due
Temp/Humidity	E005409	10-19-17	10-31-18
DC Voltage	E003314	05-03-17	05-31-18
Photometer	E003319	01-09-18	07-31-18
1 um PSL	679755	n/a	n/a
10 um PSL	167947	n/a	n/a
Flowmeter	E002471	04-20-17	04-30-18

Measurement Variable	System ID	Last Cal.	Cal. Due
Temp/Humidity	E005410	10-19-17	10-31-18
DC Voltage	E003315	05-03-17	05-31-18
Microbalance	M001324	11-02-16	11-30-18
3 um PSL	180387	n/a	n/a
Pressure	E003511	10-02-17	10-31-18

Verified

March 1, 2018
Date

INSTRUMENT CALIBRATION REPORT

Pine Environmental Services, LLC.

Tidewater MD

Instrument ID 110-010833
Description MINIRAE 2000
Calibrated 4/9/2019

Manufacturer Rae Systems
Model Number MINIRAE 2000
Serial Number 110-010833
Location Maryland
Department CATHY MOORE

Frequency 6 Months
Status Pass
Temp 24
Humidity 39

Calibration Specifications

Group # 1
Group Name ISOBUTYLENE
Stated Accy Pct of Reading

Range Acc % 0.0000
Reading Acc % 3.0000
Plus/Minus 0.00

Nom In Val / In Val	In Type	Out Val	Out Type	Fnd As	Lft As	Dev%	Pass/Fail
100.00 / 100.00	ppm	100.00	ppm	92.80	101.00	1.00%	Pass

Test Instruments Used During the Calibration (As Of Cal Entry Date)

Test Instrument ID	Description	Manufacturer	Model Number	Serial Number / Lot Number	Last Cal Date	Next Cal Date / Expiration Date
MD ISO 100PPM FBI-248-100-12	MD ISO 100PPM	Pine Environmental Services, Inc.	FBI-248-100-12	34LS-248-100	5/23/2022	
MD ZERO AIR FBI-1-25	ZERO AIR Oxygen 20.9%VOL, Nitrogen Balance	Pine Environmental Services, Inc.	31844	FBI-1-25		

Notes about this calibration

Calibration Result Calibration Successful
Who Calibrated Ryan Armstrong

Pine Environmental Services, LLC. hereby certifies that this instrument is calibrated and functions to meet the manufacturer's specifications using NIST traceable standards, or is derived from accepted values of physical constants.

Certificate of Conformance

(X) Buck BioAire™ ( ) Buck BioSlide™

Serial number: B153043 **Date Issued:** 2-6-19

Flow Calibration

The instrument listed above is in conformance with factory specifications and the flow is set to nominal using a BUCK Calibrator which is N.I.S.T. traceable to A. P. Buck, Inc. Calibration Procedure APB-1, Ver. 6.2.

QA APPROVAL BY: Thomas J. Gravenor

A.P. BUCK, INC.
7101 Presidents Drive, Suite 110
Orlando, FL 32809
Phone: 407-851-8602 • Fax: 407-851-8910

BUCK
A.P. BUCK, INC.

Attachment D

Qualifications

ABIH®

american board of industrial hygiene®

organized to improve the practice of industrial hygiene
proclaims that

Skandakumar Harshanath Abeyesekere

having met all requirements of
education, experience and examination, and
ongoing maintenance,
is hereby certified in the

COMPREHENSIVE PRACTICE
of
INDUSTRIAL HYGIENE

and has the right to use the designations

CERTIFIED INDUSTRIAL HYGIENIST

CIH®

Certificate Number	**9928 CP**
Awarded:	**May 11, 2011**
Expiration Date:	**December 1, 2021**

Susan Ripple
Chair, ABIH

Chief Executive Officer, ABIH

BOARD OF CERTIFIED SAFETY PROFESSIONALS

affirms that

Skandakumar Abeyesekere

Has applied for, met qualifications, and passed required examination(s) and is hereby authorized to use the designation

Certified Safety Professional®

in Comprehensive Practice

So long as this certificate is not suspended or revoked and the certificant renews this authorization annually and meets Continuance of Certification requirements.

Board of Examiners in witness whereof we have here unto set our hands and affixed the Seal of the Board this 7th Day of April, 2008

Paul S Adams — President

Linda Tapp — Secretary

20110 — CSP No.

INSTITUTE OF HAZARDOUS MATERIALS MANAGEMENT

THIS CERTIFIES THAT

Skandakumar Abeyeskere

HAS SUCCESSFULLY MET ALL THE REQUIREMENTS OF EDUCATION, EXPERIENCE AND EXAMINATION, AND IS HEREBY DESIGNATED A

CERTIFIED HAZARDOUS MATERIALS MANAGER
CHMM

INSTITUTE OF HAZARDOUS MATERIALS MANAGEMENT IHMM CORPORATE SEAL 1984 DISTRICT OF COLUMBIA

May 13, 2016
DATE OF CERTIFICATION

19053
CREDENTIAL NUMBER

May 31, 2021
CERTIFICATION EXPIRES

M. Patricia Buley
ACTING EXECUTIVE DIRECTOR

VALID SO LONG AS THIS CREDENTIAL IS RENEWED ACCORDING TO SCHEDULE AND IS NOT OTHERWISE REVOKED.

ANSI Accredited Program PERSONNEL CERTIFICATION

Accredited by the American National Standards Institute and the Council of Engineering and Scientific Specialty Boards

Attachment E

Floor Plan with Sampling Locations



TIDEWATER INC	**Attachment C** **Benjamin Stoddert Middle School** **Floor Plan with Sampling Locations**	Scale: N/A Project #: 5419-020 Date: May 31, 2019	**General Notes** ▲ = Sample Location



TIDEWATER INC	**Attachment C** **Benjamin Stoddert Middle School** **Floor Plan with Sampling Locations**	Scale: N/A Project #: 5419-020 Date: May 31, 2019	**General Notes** ▲ = Sample Location



TIDEWATER INC	**Attachment C** **Benjamin Stoddert Middle School** **Floor Plan with Sampling Locations**	Scale: N/A Project #: 5419-020 Date: May 31, 2019	**General Notes** ▲ = Sample Location