

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (800) 220-3675 / (856) 786-0327

<http://www.EMSL.com>cinnaminsonradonlab@emsl.com

EMSL Order: 381701333

CustomerID: PGCS62

CustomerPO:

ProjectID:

Attn: **Alex Baylor**
Prince George's County School
13306 Old Marlboro Pike
Uppr Marlboro, MD 20772

Phone: (301) 952-6760
 Fax: (301) 952-0346
 Received: 02/07/17 12:25 PM
 Analysis Date: 2/8/2017
 Collected: 2/3/2017

Project: **Croom High**

Test **Croom High**
 Site: **Cheltenham, MD 20623**

Test Report: Radon in Air Test Results

Liquid Scintillation ID	Location	Radon Activity (pCi/L)	Start	Stop	Temperature F	Humidity %	Sample Type
270539 381701333-0001	Guidance Office	0.4	2/3/2017 6:00:00 PM	2/6/2017 7:00:00 AM	76	30	Customer
Sample Notes:							
270521 381701333-0002	Guidance Office	0.4	2/3/2017 6:02:00 PM	2/6/2017 7:02:00 AM	76	30	Customer
Sample Notes:							
270475 381701333-0003	C-102	0.4	2/3/2017 6:05:00 PM	2/6/2017 7:05:00 AM	76	30	Customer
Sample Notes:							
270592 381701333-0004	C-106	0.4	2/3/2017 6:08:00 PM	2/6/2017 7:09:00 AM	76	30	Customer
Sample Notes:							
270587 381701333-0005	C-108	0.3	2/3/2017 6:11:00 PM	2/6/2017 7:12:00 AM	72	30	Customer
Sample Notes:							
270532 381701333-0006	C-114	0.4	2/3/2017 6:14:00 PM	2/6/2017 7:17:00 AM	72	30	Customer
Sample Notes:							
270594 381701333-0007	C-118	0.3	2/3/2017 6:17:00 PM	2/6/2017 7:22:00 AM	72	30	Customer
Sample Notes:							
270420 381701333-0008	C-128	0.5	2/3/2017 6:24:00 PM	2/6/2017 7:24:00 AM	66	75	Customer
Sample Notes:							
270590 381701333-0009	Library	0.9	2/3/2017 6:30:00 PM	2/6/2017 7:28:00 AM	66	75	Customer
Sample Notes:							
270490 381701333-0010	Main Office	0.5	2/3/2017 6:37:00 PM	2/6/2017 7:32:00 AM	72	30	Customer
Sample Notes:							

Please visit www.radontestinglab.com



EMSL Analytical, Inc.

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (800) 220-3675 / (856) 786-0327

<http://www.EMSL.com>

cinnaminsonradonlab@emsl.com

EMSL Order:	381701333
CustomerID:	PGCS62
CustomerPO:	
ProjectID:	

Test Report: Radon in Air Test Results

Liquid Scintillation ID	Location	Radon Activity (pCi/L)	Start	Stop	Temperature F	Humidity %	Sample Type
268783 381701333-0011	Suite B	0.3	2/3/2017 6:39:00 PM	2/6/2017 7:35:00 AM	72	30	Customer
Sample Notes:							
270599 381701333-0012	B-114	0.4	2/3/2017 6:41:00 PM	2/6/2017 7:38:00 AM	72	30	Customer
Sample Notes:							
270582 381701333-0013	B-109	0.4	2/3/2017 6:45:00 PM	2/6/2017 7:41:00 AM	72	30	Customer
Sample Notes:							
270525 381701333-0014	B-105	0.4	2/3/2017 6:48:00 PM	2/6/2017 7:44:00 AM	72	30	Customer
Sample Notes:							
270436 381701333-0015	B-131	0.2	2/3/2017 6:51:00 PM	2/6/2017 7:48:00 AM	72	30	Customer
Sample Notes:							
270596 381701333-0016	Health Room	0.3	2/3/2017 6:54:00 PM	2/6/2017 7:52:00 AM	72	30	Customer
Sample Notes:							
270591 381701333-0017	C-137	0.4	2/3/2017 6:57:00 PM	2/6/2017 7:55:00 AM	72	30	Customer
Sample Notes:							
270483 381701333-0018	C-137	0.4	2/3/2017 6:59:00 PM	2/6/2017 7:58:00 AM	72	30	Customer
Sample Notes:							

Report Notes



EMSL Analytical, Inc.

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (800) 220-3675 / (856) 786-0327

<http://www.EMSL.com>

cinnaminsonradonlab@emsl.com

EMSL Order:	381701333
CustomerID:	PGCS62
CustomerPO:	
ProjectID:	

Test Report: Radon in Air Test Results

Liquid Scintillation ID	Location	Radon Activity (pCi/L)	Start	Stop	Temperature F	Humidity %	Sample Type
-------------------------	----------	------------------------	-------	------	---------------	------------	-------------

The United States Environmental Protection Agency (EPA) has established a radon action level of 4.0pCi/L. EPA recommends mitigation of a structure if the confirmed radon level is equal to or greater than 4.0pCi/L.

The radon tests were performed using liquid scintillation radon detectors and counted on a liquid scintillation counter following EPA Method # 402-R-92-004 testing protocol for Radon in Air testing. EPA recommends retesting every two years.

Please contact EMSL Analytical, Inc. or your State Health Department for further information.

All procedures used for generating this report are in complete accordance with the current EPA protocols for the analysis of Radon in Air.

Analyst(s)

Racquel Hafiz (18)

Laura Freeman, Radon Laboratory Manager &
Peixue Ma, Ph.D, NJ Radon Measurement Specialist NJ MES
13502

In no event shall EMSL be liable for indirect, special, consequential, or incidental damages, including, but not limited to, damages for loss of profit or goodwill regardless of the negligence (either sole or concurrent) of EMSL and whether EMSL has been informed of the possibility of such damages, arising out of or in connection with EMSL's services thereunder or the delivery, use, reliance upon or interpretation of test results by client or any third party. We accept no legal responsibility for the purposes for which the client uses the test results. In no event shall EMSL be liable to a client or any third party, whether based upon theories of tort, contract or any other legal or equitable theory, in excess of the amount paid to EMSL by client thereunder. The test results meets all NELAC requirements unless otherwise specified.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ Accreditations: NRSB ARL6006, NJ DEP 03036, MEB 92525, PA 2573, IN 00455, IA L00032, RI RAS-024, ME 20200C, NE RMB-1083, NY ELAP 10872, NM 885-10L, FL RB2034, OH RL-39, NRPP #106178AL, KS-LB-0005, IL RNL2008202..

Initial report from 02/10/2017 12:16:03