

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077
 Phone/Fax: (800) 220-3675 / (856) 786-0327
<http://www.EMSL.com> cinnaminsonradonlab@emsl.com

EMSL Order: 381612381
 CustomerID: PGCS62
 CustomerPO:
 ProjectID:

Attn: **Alex Baylor**
Prince George's County School
13306 Old Marlboro Pike
Uppr Marlboro, MD 20772

Phone: (301) 952-6760
 Fax: (301) 952-0346
 Received: 11/16/16 12:12 PM
 Analysis Date: 11/18/2016
 Collected: 11/11/2016

Project: **Dwight Eisenhower Middle School**

Test Site: **Dwight Eisenhower**
13725 Briarwood Dr
Laurel, MD 20708

Test Report: Radon in Air Test Results**Samples for EMSL Kit 144205**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
242748	Main Office	0.4	11/11/2016	11/14/2016	70	50	Customer
381612381-0001			1:35:00 PM	8:17:00 AM			

Sample Notes:

243694	Main Office	-0.1	11/11/2016	11/14/2016	70	50	Blank
381612381-0002			1:35:00 PM	8:17:00 AM			

Sample Notes:**Samples for EMSL Kit 144192**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
242725	Room 101A	1.7	11/11/2016	11/14/2016	70	50	Customer
381612381-0003			1:41:00 PM	8:19:00 AM			

Sample Notes:

243774	Room 101A	1.8	11/11/2016	11/14/2016	70	50	Duplicate
381612381-0004			1:41:00 PM	8:19:00 AM			

Sample Notes:

Duplicate RPD = 5.7%

Samples for EMSL Kit 144200

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
242791	Room 102	0.5	11/11/2016	11/14/2016	70	50	Customer
381612381-0005			1:43:00 PM	8:21:00 AM			

Sample Notes:**Samples for EMSL Kit 144133**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
242888	Room 107	0.9	11/11/2016	11/14/2016	70	50	Customer
381612381-0006			1:45:00 PM	8:21:00 AM			

Sample Notes:

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (800) 220-3675 / (856) 786-0327

<http://www.EMSL.com>cinnaminsonradonlab@emsl.com

EMSL Order: 381612381

CustomerID: PGCS62

CustomerPO:

ProjectID:

Attn: **Alex Baylor**
Prince George's County School
13306 Old Marlboro Pike
Uppr Marlboro, MD 20772

Phone: (301) 952-6760
 Fax: (301) 952-0346
 Received: 11/16/16 12:12 PM
 Analysis Date: 11/18/2016
 Collected: 11/11/2016

Project: **Dwight Eisenhower Middle School**

Test Site: **Dwight Eisenhower**
13725 Briarwood Dr
Laurel, MD 20708

Test Report: Radon in Air Test Results**Samples for EMSL Kit 144193**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
242741	Library	1.1	11/11/2016	11/14/2016	70	50	Customer
381612381-0007			1:46:00 PM	8:22:00 AM			

Sample Notes:**Samples for EMSL Kit 144125**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
242834	Room 108	0.8	11/11/2016	11/14/2016	70	50	Customer
381612381-0008			1:48:00 PM	8:23:00 AM			

Sample Notes:

243590	Room 108	0.2	11/11/2016	11/14/2016	70	50	Blank
381612381-0009			1:48:00 PM	8:23:00 AM			

Sample Notes:**Samples for EMSL Kit 144122**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
242813	Room 112	1.3	11/11/2016	11/14/2016	70	50	Customer
381612381-0010			1:50:00 PM	8:24:00 AM			

Sample Notes:

243764	Room 112	1.5	11/11/2016	11/14/2016	70	50	Duplicate
381612381-0011			1:50:00 PM	8:24:00 AM			

Sample Notes:**Duplicate RPD = 14.3%****Samples for EMSL Kit 144201**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
242728	Exercise Room	0.3	11/11/2016	11/14/2016	70	50	Customer
381612381-0012			1:52:00 PM	8:25:00 AM			

Sample Notes:

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077
 Phone/Fax: (800) 220-3675 / (856) 786-0327
<http://www.EMSL.com> cinnaminsonradonlab@emsl.com

EMSL Order: 381612381
 CustomerID: PGCS62
 CustomerPO:
 ProjectID:

Attn: **Alex Baylor**
Prince George's County School
13306 Old Marlboro Pike
Uppr Marlboro, MD 20772

Phone: (301) 952-6760
 Fax: (301) 952-0346
 Received: 11/16/16 12:12 PM
 Analysis Date: 11/18/2016
 Collected: 11/11/2016

Project: **Dwight Eisenhower Middle School**

Test Site: **Dwight Eisenhower**
13725 Briarwood Dr
Laurel, MD 20708

Test Report: Radon in Air Test Results**Samples for EMSL Kit 144153**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
242812	Room A4	0.8	11/11/2016	11/14/2016	70	50	Customer
381612381-0013			1:55:00 PM	8:26:00 AM			

Sample Notes:

Samples for EMSL Kit 144216

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
242752	Band Room	0.7	11/11/2016	11/14/2016	70	50	Customer
381612381-0014			1:56:00 PM	8:16:00 AM			

Sample Notes:

Samples for EMSL Kit 144111

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
242826	Stage	0.9	11/11/2016	11/14/2016	70	50	Customer
381612381-0015			1:57:00 PM	8:17:00 AM			

Sample Notes:

The radon test was performed using a liquid scintillation radon detector/s and counted on a liquid scintillation counter using approved EPA testing protocols for Radon in Air testing. The EPA recommends fixing your home if the average of two short-term tests taken in the lowest lived-in level of the home show radon levels that are equal to or greater than 4.0pCi/L. The EPA recommends retesting your home every two years.

Please contact EMSL Analytical, Inc. or your State Health Department for further information. All procedures used for generating this report are in complete accordance with the current EPA protocols for the analysis of Radon in Air.

Report Note

