

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077
 Phone/Fax: (800) 220-3675 / (856) 786-0327
<http://www.EMSL.com> cinnaminsonradonlab@emsl.com

EMSL Order: 381602734
 CustomerID: PGCS62
 CustomerPO:
 ProjectID:

Attn: **Karen Bowlding**
Prince George's County School
13300 Old Marlboro Pike
Upper Marlboro, MD 20772

Phone: (301) 952-6559
 Fax: (301) 952-0346
 Received: 03/24/16 10:50 AM
 Analysis Date: 3/25/2016
 Collected: 3/18/2016

Project: **Hollywood**

Test Site: **Hollywood**
College Park, MD 20740

Test Report: Radon in Air Test Results**Samples for EMSL Kit 142006**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
240696	Main Office	0.3	3/18/2016	3/21/2016	70	50	Customer
381602734-0001			1:00:00 PM	8:20:00 PM			

Sample Notes:

Samples for EMSL Kit 142018

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
240664	Room #1	0.4	3/18/2016	3/21/2016	70	50	Customer
381602734-0002			1:02:00 PM	8:22:00 PM			

Sample Notes:

238249	Room #1	-0.1	3/18/2016	3/21/2016	70	50	Duplicate
381602734-0003			1:02:00 PM	8:22:00 PM			

Sample Notes:

Duplicate RPD = 200%

Samples for EMSL Kit 141964

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
240722	Room #4	0.2	3/18/2016	3/21/2016	70	50	Customer
381602734-0004			1:03:00 PM	8:24:00 PM			

Sample Notes:

Samples for EMSL Kit 142015

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
240108	Room #5	0.5	3/18/2016	3/21/2016	70	50	Customer
381602734-0005			1:05:00 PM	8:30:00 PM			

Sample Notes:

239923	Room #5	0	3/18/2016	3/21/2016	70	50	Blank
381602734-0006			1:05:00 PM	8:30:00 PM			

Sample Notes:

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077
 Phone/Fax: (800) 220-3675 / (856) 786-0327
<http://www.EMSL.com> cinnaminsonradonlab@emsl.com

EMSL Order: 381602734
 CustomerID: PGCS62
 CustomerPO:
 ProjectID:

Attn: **Karen Bowlding**
Prince George's County School
13300 Old Marlboro Pike
Upper Marlboro, MD 20772

Phone: (301) 952-6559
 Fax: (301) 952-0346
 Received: 03/24/16 10:50 AM
 Analysis Date: 3/25/2016
 Collected: 3/18/2016

Project: **Hollywood**

Test Site: **Hollywood**
College Park, MD 20740

Test Report: Radon in Air Test Results**Samples for EMSL Kit 142005**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
239752	Room #9	0.1	3/18/2016	3/21/2016	70	50	Customer
381602734-0007			1:07:00 PM	8:33:00 PM			

Sample Notes:

237952	Room #9	0	3/18/2016	3/21/2016	70	50	Blank
381602734-0008			1:07:00 PM	8:33:00 PM			

Sample Notes:**Samples for EMSL Kit 141966**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
	Room #11		3/18/2016	3/21/2016	70	50	Customer
381602734-0009			1:08:00 PM	8:40:00 PM			

Sample Notes: Not Analyzed
 Radon kit not received by lab.

Samples for EMSL Kit 142004

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
239753	Room #8	0.2	3/18/2016	3/21/2016	70	50	Customer
381602734-0010			1:10:00 PM	8:42:00 PM			

Sample Notes:**Samples for EMSL Kit 142016**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
240087	Room #17	0.3	3/18/2016	3/21/2016	70	50	Customer
381602734-0011			1:11:00 PM	8:45:00 PM			

Sample Notes:

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077
 Phone/Fax: (800) 220-3675 / (856) 786-0327
<http://www.EMSL.com> cinnaminsonradonlab@emsl.com

EMSL Order: 381602734
 CustomerID: PGCS62
 CustomerPO:
 ProjectID:

Attn: **Karen Bowlding**
Prince George's County School
13300 Old Marlboro Pike
Upper Marlboro, MD 20772

Phone: (301) 952-6559
 Fax: (301) 952-0346
 Received: 03/24/16 10:50 AM
 Analysis Date: 3/25/2016
 Collected: 3/18/2016

Project: **Hollywood**

Test Site: **Hollywood**
College Park, MD 20740

Test Report: Radon in Air Test Results**Samples for EMSL Kit 142023**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
240644	Media Center	0.2	3/18/2016	3/21/2016	70	50	Customer
381602734-0012			1:13:00 PM	8:47:00 PM			

Sample Notes:

Samples for EMSL Kit 142017

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
240085	Teacher's Lounge	0.6	3/18/2016	3/21/2016	70	50	Customer
381602734-0013			1:16:00 PM	8:50:00 PM			

Sample Notes:

Samples for EMSL Kit 142007

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
239751	Room #12	0.9	3/18/2016	3/21/2016	70	50	Customer
381602734-0014			1:18:00 PM	8:51:00 PM			

Sample Notes:

Samples for EMSL Kit 142019

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
239754	Spec. Ed	0.3	3/18/2016	3/21/2016	70	50	Customer
381602734-0015			1:21:00 PM	8:53:00 PM			

Sample Notes:

Samples for EMSL Kit 142025

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
240652	Music Room	0.2	3/18/2016	3/21/2016	70	50	Customer
381602734-0016			1:30:00 PM	8:55:00 PM			

Sample Notes:

239816	Music Room	0	3/18/2016	3/21/2016	70	50	Blank
381602734-0017			1:30:00 PM	8:55:00 PM			

Sample Notes:



EMSL Analytical, Inc.

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (800) 220-3675 / (856) 786-0327

<http://www.EMSL.com>

cinnaminsonradonlab@emsl.com

EMSL Order:	381602734
CustomerID:	PGCS62
CustomerPO:	
ProjectID:	

Attn: **Karen Bowlding**
Prince George's County School
13300 Old Marlboro Pike
Upper Marlboro, MD 20772

Phone: (301) 952-6559
 Fax: (301) 952-0346
 Received: 03/24/16 10:50 AM
 Analysis Date: 3/25/2016
 Collected: 3/18/2016

Project: **Hollywood**

Test Site: **Hollywood**
College Park, MD 20740

Test Report: Radon in Air Test Results

The radon test was performed using a liquid scintillation radon detector/s and counted on a liquid scintillation counter using approved EPA testing protocols for Radon in Air testing. The EPA recommends fixing your home if the average of two short-term tests taken in the lowest lived-in level of the home show radon levels that are equal to or greater than 4.0pCi/L. The EPA recommends retesting your home every two years.

Please contact EMSL Analytical, Inc. or your State Health Department for further information.

All procedures used for generating this report are in complete accordance with the current EPA protocols for the analysis of Radon in Air.

Report Note

Analyst(s)

Tiffanie Cosgrove (16)



Laura Freeman, Interim Laboratory Manager &
 Subash Rashat, New Jersey Radiation Specialist NJ MES 10152
 or other approved signatory

In no event shall EMSL be liable for indirect, special, consequential, or incidental damages, including, but not limited to, damages for loss of profit or goodwill regardless of the negligence (either sole or concurrent) of EMSL and whether EMSL has been informed of the possibility of such damages, arising out of or in connection with EMSL's services thereunder or the delivery, use, reliance upon or interpretation of test results by client or any third party. We accept no legal responsibility for the purposes for which the client uses the test results. In no event shall EMSL be liable to a client or any third party, whether based upon theories of tort, contract or any other legal or equitable theory, in excess of the amount paid to EMSL by client thereunder. The test results meets all NELAC requirements unless otherwise specified. Accreditations: NRSB ARL6006, NJ DEP 03036, MEB 92525, PA 2573, IN 00455, IA L00032, RI RAS-024, ME 20200C, NE RMB-1083, NY ELAP 10872, NM 885-10L, FL RB2034, OH RL-39, NRPP #106178AL, KS-LB-0005

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ Accreditations: NRSB ARL6006, NJ DEP 03036, MEB 92525, PA 2573, IN 00455, IA L00032, RI RAS-024, ME 20200C, NE RMB-1083, NY ELAP 10872, NM 885-10L, FL RB2034, OH RL-39, NRPP #106178AL, KS-LB-0005. Subash Rashat certification #MES10152

Initial report from 03/31/2016 19:21:26

Please visit www.radontestinglab.com