

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077
 Phone/Fax: (800) 220-3675 / (856) 786-0327
<http://www.EMSL.com> cinnaminsonradonlab@emsl.com

EMSL Order: 381603510
 CustomerID: PGCS62
 CustomerPO:
 ProjectID:

Attn: **Karen Bowlding**
Prince George's County School
13300 Old Marlboro Pike
Upper Marlboro, MD 20772

Phone: (301) 952-6559
 Fax: (301) 952-0346
 Received: 04/08/16 10:33 AM
 Analysis Date: 4/13/2016
 Collected: 4/1/2016

Project: **Judge S. Woods ES**

Test Site: **Judge S. Woods ES**
Glenarden, MD 20706

Test Report: Radon in Air Test Results**Samples for EMSL Kit 143325**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
241351 381603510-0001	Main Office	0.9	4/1/2016 10:03:00 AM	4/4/2016 10:53:00 AM	70	50	Customer

Sample Notes:

240266 381603510-0002	Main Office	-0.1	4/1/2016 10:03:00 AM	4/4/2016 10:53:00 AM	70	50	Blank
--------------------------	-------------	------	-------------------------	-------------------------	----	----	-------

Sample Notes:**Samples for EMSL Kit 143326**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
241610 381603510-0003	Library	0.8	4/1/2016 10:04:00 AM	4/4/2016 11:16:00 AM	70	50	Customer

Sample Notes:**Samples for EMSL Kit 143338**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
241218 381603510-0004	Room 41	0	4/1/2016 10:15:00 AM	4/4/2016 11:39:00 AM	70	50	Customer

Sample Notes:

241630 381603510-0005	Room 41	0	4/1/2016 10:15:00 AM	4/4/2016 11:39:00 AM	70	50	Duplicate
--------------------------	---------	---	-------------------------	-------------------------	----	----	-----------

Sample Notes:**Duplicate RPD = 0%****Samples for EMSL Kit 143323**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
241353 381603510-0006	Room 40	0.3	4/1/2016 10:16:00 AM	4/4/2016 11:17:00 AM	70	50	Customer

Sample Notes:

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (800) 220-3675 / (856) 786-0327

<http://www.EMSL.com>cinnaminsonradonlab@emsl.com

EMSL Order: 381603510

CustomerID: PGCS62

CustomerPO:

ProjectID:

Attn: **Karen Bowlding**
Prince George's County School
13300 Old Marlboro Pike
Upper Marlboro, MD 20772

Phone: (301) 952-6559
 Fax: (301) 952-0346
 Received: 04/08/16 10:33 AM
 Analysis Date: 4/13/2016
 Collected: 4/1/2016

Project: **Judge S. Woods ES**

Test Site: **Judge S. Woods ES**
Glenarden, MD 20706

Test Report: Radon in Air Test Results**Samples for EMSL Kit 143334**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
241208	Room 39	0.9	4/1/2016	4/4/2016	70	50	Customer
381603510-0007			10:18:00 AM	11:18:00 AM			

Sample Notes:**Samples for EMSL Kit 143346**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
241251	Room 38	0.8	4/1/2016	4/4/2016	70	50	Customer
381603510-0008			10:20:00 AM	11:19:00 AM			

Sample Notes:**Samples for EMSL Kit 143339**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
241238	Room 37	0	4/1/2016	4/4/2016	70	50	Customer
381603510-0009			10:22:00 AM	11:20:00 AM			

Sample Notes:**Samples for EMSL Kit 143327**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
241339	Room 36	0	4/1/2016	4/4/2016	70	50	Customer
381603510-0010			10:24:00 AM	11:21:00 AM			

Sample Notes:**Samples for EMSL Kit 143336**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
241273	Room 35	1.7	4/1/2016	4/4/2016	70	50	Customer
381603510-0011			10:26:00 AM	11:23:00 AM			

Sample Notes:

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077
 Phone/Fax: (800) 220-3675 / (856) 786-0327
<http://www.EMSL.com> cinnaminsonradonlab@emsl.com

EMSL Order: 381603510
 CustomerID: PGCS62
 CustomerPO:
 ProjectID:

Attn: **Karen Bowlding**
Prince George's County School
13300 Old Marlboro Pike
Upper Marlboro, MD 20772

Phone: (301) 952-6559
 Fax: (301) 952-0346
 Received: 04/08/16 10:33 AM
 Analysis Date: 4/13/2016
 Collected: 4/1/2016

Project: **Judge S. Woods ES**

Test Site: **Judge S. Woods ES**
Glenarden, MD 20706

Test Report: Radon in Air Test Results**Samples for EMSL Kit 143337**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
241320	Room 33	0.4	4/1/2016	4/4/2016	70	50	Customer
381603510-0012			10:28:00 AM	11:24:00 AM			

Sample Notes:

Samples for EMSL Kit 143315

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
241290	Room 34	0.1	4/1/2016	4/4/2016	70	50	Customer
381603510-0013			10:30:00 AM	11:25:00 AM			

Sample Notes:

240300	Room 34	0	4/1/2016	4/4/2016	70	50	Blank
381603510-0014			10:30:00 AM	11:25:00 AM			

Sample Notes:

Samples for EMSL Kit 143314

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
241276	Room 32	0.1	4/1/2016	4/4/2016	70	50	Customer
381603510-0015			10:32:00 AM	11:26:00 AM			

Sample Notes:

Samples for EMSL Kit 143367

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
241224	TV Room	0	4/1/2016	4/4/2016	70	50	Customer
381603510-0016			10:33:00 AM	11:40:00 AM			

Sample Notes:

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077
 Phone/Fax: (800) 220-3675 / (856) 786-0327
<http://www.EMSL.com> cinnaminsonradonlab@emsl.com

EMSL Order: 381603510
 CustomerID: PGCS62
 CustomerPO:
 ProjectID:

Attn: **Karen Bowlding**
Prince George's County School
13300 Old Marlboro Pike
Upper Marlboro, MD 20772

Phone: (301) 952-6559
 Fax: (301) 952-0346
 Received: 04/08/16 10:33 AM
 Analysis Date: 4/13/2016
 Collected: 4/1/2016

Project: **Judge S. Woods ES**

Test Site: **Judge S. Woods ES**
Glenarden, MD 20706

Test Report: Radon in Air Test Results**Samples for EMSL Kit 143312**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
241370	Room 30	0.3	4/1/2016	4/4/2016	70	50	Customer
381603510-0017			10:34:00 AM	11:27:00 AM			

Sample Notes:

241579	Room 30	0.3	4/1/2016	4/4/2016	70	50	Duplicate
381603510-0018			10:34:00 AM	11:27:00 AM			

Sample Notes:**Duplicate RPD = 0%****Samples for EMSL Kit 143324**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
241277	Room 29	0	4/1/2016	4/4/2016	70	50	Customer
381603510-0019			10:35:00 AM	11:28:00 AM			

Sample Notes:**Samples for EMSL Kit 143313**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
241487	Waiting Room	1.2	4/1/2016	4/4/2016	70	50	Customer
381603510-0020			10:36:00 AM	11:29:00 AM			

Sample Notes:**Samples for EMSL Kit 143335**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
241243	Teacher Work Room #2	0.5	4/1/2016	4/4/2016	70	50	Customer
381603510-0021			10:30:00 AM	11:22:00 AM			

Sample Notes:

240255	Teacher Work Room #2	-0.1	4/1/2016	4/4/2016	70	50	Blank
381603510-0022			10:30:00 AM	11:22:00 AM			

Sample Notes:

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077
 Phone/Fax: (800) 220-3675 / (856) 786-0327
<http://www.EMSL.com> cinnaminsonradonlab@emsl.com

EMSL Order: 381603510
 CustomerID: PGCS62
 CustomerPO:
 ProjectID:

Attn: **Karen Bowlding**
Prince George's County School
13300 Old Marlboro Pike
Upper Marlboro, MD 20772

Phone: (301) 952-6559
 Fax: (301) 952-0346
 Received: 04/08/16 10:33 AM
 Analysis Date: 4/13/2016
 Collected: 4/1/2016

Project: **Judge S. Woods ES**

Test Site: **Judge S. Woods ES**
Glenarden, MD 20706

Test Report: Radon in Air Test Results**Samples for EMSL Kit 143348**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
241259	Room 28	0	4/1/2016	4/4/2016	70	50	Customer
381603510-0023			10:31:00 AM	11:30:00 AM			

Sample Notes:

241623	Room 28	-0.1	4/1/2016	4/4/2016	70	50	Duplicate
381603510-0024			10:31:00 AM	11:30:00 AM			

Sample Notes:**Duplicate RPD = 0%****Samples for EMSL Kit 143347**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
241249	Room 27	0.7	4/1/2016	4/4/2016	70	50	Customer
381603510-0025			10:38:00 AM	11:31:00 AM			

Sample Notes:**Samples for EMSL Kit 143378**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
241430	Room 26	0.1	4/1/2016	4/4/2016	70	50	Customer
381603510-0026			10:39:00 AM	11:32:00 AM			

Sample Notes:

241569	Room 26	0.4	4/1/2016	4/4/2016	70	50	Duplicate
381603510-0027			10:39:00 AM	11:32:00 AM			

Sample Notes:**Duplicate RPD = 120%****Samples for EMSL Kit 143422**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
242027	Room 25	0.8	4/1/2016	4/4/2016	70	50	Customer
381603510-0028			10:40:00 AM	11:33:00 AM			

Sample Notes:

241605	Room 25	0.3	4/1/2016	4/4/2016	70	50	Duplicate
381603510-0029			10:40:00 AM	11:33:00 AM			

Sample Notes:**Duplicate RPD = 90.9%**

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077
 Phone/Fax: (800) 220-3675 / (856) 786-0327
<http://www.EMSL.com> cinnaminsonradonlab@emsl.com

EMSL Order: 381603510
 CustomerID: PGCS62
 CustomerPO:
 ProjectID:

Attn: **Karen Bowlding**
Prince George's County School
13300 Old Marlboro Pike
Upper Marlboro, MD 20772

Phone: (301) 952-6559
 Fax: (301) 952-0346
 Received: 04/08/16 10:33 AM
 Analysis Date: 4/13/2016
 Collected: 4/1/2016

Project: **Judge S. Woods ES**

Test Site: **Judge S. Woods ES**
Glenarden, MD 20706

Test Report: Radon in Air Test Results**Samples for EMSL Kit 143423**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
241211	Room 24	0.7	4/1/2016	4/4/2016	70	50	Customer
381603510-0030			10:40:00 AM	11:34:00 AM			

Sample Notes:

Samples for EMSL Kit 143413

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
241991	Room 23	0.4	4/1/2016	4/4/2016	70	50	Customer
381603510-0031			10:41:00 AM	11:35:00 AM			

Sample Notes:

Samples for EMSL Kit 143400

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
241957	Room 22	0.1	4/1/2016	4/4/2016	70	50	Customer
381603510-0032			10:42:00 AM	11:36:00 AM			

Sample Notes:

Samples for EMSL Kit 143415

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
241268	Room 21	0.3	4/1/2016	4/4/2016	70	50	Customer
381603510-0033			10:44:00 AM	11:37:00 AM			

Sample Notes:

240529	Room 21	-0.3	4/1/2016	4/4/2016	70	50	Blank
381603510-0034			10:44:00 AM	11:37:00 AM			

Sample Notes:

Samples for EMSL Kit 143410

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
241240	Room 20	0	4/1/2016	4/4/2016	70	50	Customer
381603510-0035			10:45:00 AM	11:38:00 AM			

Sample Notes:

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077
 Phone/Fax: (800) 220-3675 / (856) 786-0327
<http://www.EMSL.com> cinnaminsonradonlab@emsl.com

EMSL Order: 381603510
 CustomerID: PGCS62
 CustomerPO:
 ProjectID:

Attn: **Karen Bowlding**
Prince George's County School
13300 Old Marlboro Pike
Upper Marlboro, MD 20772

Phone: (301) 952-6559
 Fax: (301) 952-0346
 Received: 04/08/16 10:33 AM
 Analysis Date: 4/13/2016
 Collected: 4/1/2016

Project: **Judge S. Woods ES**

Test Site: **Judge S. Woods ES**
Glenarden, MD 20706

Test Report: Radon in Air Test Results**Samples for EMSL Kit 143406**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
241981	Room 19	0.4	4/1/2016	4/4/2016	70	50	Customer
381603510-0036			10:46:00 AM	11:02:00 AM			

Sample Notes:

Samples for EMSL Kit 143419

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
241962	Room 18	0.6	4/1/2016	4/4/2016	70	50	Customer
381603510-0037			10:47:00 AM	11:01:00 AM			

Sample Notes:

Samples for EMSL Kit 143388

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
241209	Room 17	0.4	4/1/2016	4/4/2016	70	50	Customer
381603510-0038			10:48:00 AM	11:00:00 AM			

Sample Notes:

241524	Room 17	0.6	4/1/2016	4/4/2016	70	50	Duplicate
381603510-0039			10:48:00 AM	11:00:00 AM			

Sample Notes:

Duplicate RPD = 40%

Samples for EMSL Kit 143387

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
241932	Room 16	0.3	4/1/2016	4/4/2016	70	50	Customer
381603510-0040			10:49:00 AM	11:03:00 AM			

Sample Notes:

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077
 Phone/Fax: (800) 220-3675 / (856) 786-0327
<http://www.EMSL.com> cinnaminsonradonlab@emsl.com

EMSL Order: 381603510
 CustomerID: PGCS62
 CustomerPO:
 ProjectID:

Attn: **Karen Bowlding**
Prince George's County School
13300 Old Marlboro Pike
Upper Marlboro, MD 20772

Phone: (301) 952-6559
 Fax: (301) 952-0346
 Received: 04/08/16 10:33 AM
 Analysis Date: 4/13/2016
 Collected: 4/1/2016

Project: **Judge S. Woods ES**

Test Site: **Judge S. Woods ES**
Glenarden, MD 20706

Test Report: Radon in Air Test Results**Samples for EMSL Kit 143385**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
241230	Room 15	0.1	4/1/2016	4/4/2016	70	50	Customer
381603510-0041			10:50:00 AM	11:04:00 AM			

Sample Notes:

240337	Room 15	0.1	4/1/2016	4/4/2016	70	50	Blank
381603510-0042			10:50:00 AM	11:04:00 AM			

Sample Notes:**Samples for EMSL Kit 143399**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
241959	Room 14	0.6	4/1/2016	4/4/2016	70	50	Customer
381603510-0043			10:51:00 AM	11:05:00 AM			

Sample Notes:**Samples for EMSL Kit 143384**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
241231	Room 13A	0.1	4/1/2016	4/4/2016	70	50	Customer
381603510-0044			10:52:00 AM	11:06:00 AM			

Sample Notes:**Samples for EMSL Kit 143383**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
241221	Room 12	1	4/1/2016	4/4/2016	70	50	Customer
381603510-0045			10:53:00 AM	11:07:00 AM			

Sample Notes:

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077
 Phone/Fax: (800) 220-3675 / (856) 786-0327
<http://www.EMSL.com> cinnaminsonradonlab@emsl.com

EMSL Order: 381603510
 CustomerID: PGCS62
 CustomerPO:
 ProjectID:

Attn: **Karen Bowlding**
Prince George's County School
13300 Old Marlboro Pike
Upper Marlboro, MD 20772

Phone: (301) 952-6559
 Fax: (301) 952-0346
 Received: 04/08/16 10:33 AM
 Analysis Date: 4/13/2016
 Collected: 4/1/2016

Project: **Judge S. Woods ES**

Test Site: **Judge S. Woods ES**
Glenarden, MD 20706

Test Report: Radon in Air Test Results**Samples for EMSL Kit 143395**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
242105	Room 10	0.7	4/1/2016	4/4/2016	70	50	Customer
381603510-0046			10:54:00 AM	11:08:00 AM			

Sample Notes:

240253	Room 10	0	4/1/2016	4/4/2016	70	50	Blank
381603510-0047			10:54:00 AM	11:08:00 AM			

Sample Notes:**Samples for EMSL Kit 143394**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
241361	Room 11	0.3	4/1/2016	4/4/2016	70	50	Customer
381603510-0048			10:55:00 AM	11:09:00 AM			

Sample Notes:**Samples for EMSL Kit 143407**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
241201	Room 8	0.3	4/1/2016	4/4/2016	70	50	Customer
381603510-0049			10:56:00 AM	11:10:00 AM			

Sample Notes:**Samples for EMSL Kit 143397**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
241884	Room 6	0.4	4/1/2016	4/4/2016	70	50	Customer
381603510-0050			10:57:00 AM	11:11:00 AM			

Sample Notes:**Samples for EMSL Kit 143409**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
242009	Room 5	0.1	4/1/2016	4/4/2016	70	50	Customer
381603510-0051			10:58:00 AM	11:12:00 AM			

Sample Notes:

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077
 Phone/Fax: (800) 220-3675 / (856) 786-0327
<http://www.EMSL.com> cinnaminsonradonlab@emsl.com

EMSL Order: 381603510
 CustomerID: PGCS62
 CustomerPO:
 ProjectID:

Attn: **Karen Bowlding**
Prince George's County School
13300 Old Marlboro Pike
Upper Marlboro, MD 20772

Phone: (301) 952-6559
 Fax: (301) 952-0346
 Received: 04/08/16 10:33 AM
 Analysis Date: 4/13/2016
 Collected: 4/1/2016

Project: **Judge S. Woods ES**

Test Site: **Judge S. Woods ES**
Glenarden, MD 20706

Test Report: Radon in Air Test Results**Samples for EMSL Kit 143398**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
241539	Room 4	0.7	4/1/2016	4/4/2016	70	50	Customer
381603510-0052			10:59:00 AM	11:13:00 AM			

Sample Notes:

242023	Room 4	0.9	4/1/2016	4/4/2016	70	50	Duplicate
381603510-0053			10:59:00 AM	11:13:00 AM			

Sample Notes:**Duplicate RPD = 25%****Samples for EMSL Kit 143396**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
242056	Room 3	0.9	4/1/2016	4/4/2016	70	50	Customer
381603510-0054			11:00:00 AM	11:14:00 AM			

Sample Notes:**Samples for EMSL Kit 143408**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
242003	Room 2	0.4	4/1/2016	4/4/2016	70	50	Customer
381603510-0055			11:01:00 AM	11:15:00 AM			

Sample Notes:

241557	Room 2	0.9	4/1/2016	4/4/2016	70	50	Duplicate
381603510-0056			11:01:00 AM	11:15:00 AM			

Sample Notes:**Duplicate RPD = 76.9%**

The radon test was performed using a liquid scintillation radon detector/s and counted on a liquid scintillation counter using approved EPA testing protocols for Radon in Air testing. The EPA recommends fixing your home if the average of two short-term tests taken in the lowest lived-in level of the home show radon levels that are equal to or greater than 4.0pCi/L. The EPA recommends retesting your home every two years.

Please contact EMSL Analytical, Inc. or your State Health Department for further information.
 All procedures used for generating this report are in complete accordance with the current EPA protocols for the analysis of Radon in Air.

Report Note



EMSL Analytical, Inc.

200 Route 130 North, Cinnaminson, NJ 08077
Phone/Fax: (800) 220-3675 / (856) 786-0327
<http://www.EMSL.com> cinnaminsonradonlab@emsl.com

EMSL Order: 381603510
CustomerID: PGCS62
CustomerPO:
ProjectID:

Attn: **Karen Bowlding**
Prince George's County School
13300 Old Marlboro Pike
Upper Marlboro, MD 20772

Phone: (301) 952-6559
Fax: (301) 952-0346
Received: 04/08/16 10:33 AM
Analysis Date: 4/13/2016
Collected: 4/1/2016

Project: **Judge S. Woods ES**

Test Site: **Judge S. Woods ES**
Glenarden, MD 20706

Test Report: Radon in Air Test Results

Analyst(s)

Tiffanie Cosgrove (56)

Laura Freeman, Interim Laboratory Manager &
Subash Rashat, New Jersey Radiation Specialist NJ MES 10152
or other approved signatory

In no event shall EMSL be liable for indirect, special, consequential, or incidental damages, including, but not limited to, damages for loss of profit or goodwill regardless of the negligence (either sole or concurrent) of EMSL and whether EMSL has been informed of the possibility of such damages, arising out of or in connection with EMSL's services thereunder or the delivery, use, reliance upon or interpretation of test results by client or any third party. We accept no legal responsibility for the purposes for which the client uses the test results. In no event shall EMSL be liable to a client or any third party, whether based upon theories of tort, contract or any other legal or equitable theory, in excess of the amount paid to EMSL by client thereunder. The test results meets all NELAC requirements unless otherwise specified. Accreditations: NRSB ARL6006, NJ DEP 03036, MEB 92525, PA 2573, IN 00455, IA L00032, RI RAS-024, ME 20200C, NE RMB-1083, NY ELAP 10872, NM 885-10L, FL RB2034, OH RL-39, NRPP #106178AL, KS-LB-0005

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ Accreditations: NRSB ARL6006, NJ DEP 03036, MEB 92525, PA 2573, IN 00455, IA L00032, RI RAS-024, ME 20200C, NE RMB-1083, NY ELAP 10872, NM 885-10L, FL RB2034, OH RL-39, NRPP #106178AL, KS-LB-0005. Subash Rashat certification #MES10152

Initial report from 04/15/2016 17:49:43

Please visit www.radontestinglab.com