

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077
 Phone/Fax: (800) 220-3675 / (856) 786-0327
<http://www.EMSL.com> cinnaminsonradonlab@emsl.com

EMSL Order: 381600881
 CustomerID: PGCS62
 CustomerPO: 608048
 ProjectID:

Attn: **Karen Bowlding**
Prince George's County School
13300 Old Marlboro Pike
Upper Marlboro, MD 20772

Phone: (301) 952-6559
 Fax: (301) 952-0346
 Received: 02/02/16 1:49 PM
 Analysis Date: 2/4/2016
 Collected: 1/29/2016

Project: **Mattaponi ES**

Test Site: **Prince George's County School**
Mattaponi ES
Upper Marlboro, MD 20772

Test Report: Radon in Air Test Results**Samples for EMSL Kit 135663**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
229379	Main Office	0.1	1/29/2016	2/1/2016	65	40	Customer
381600881-0001			1:04:00 PM	7:42:00 AM			

Sample Notes:

229264	Main Office	0.1	1/29/2016	2/1/2016	65	40	Customer
381600881-0002			1:05:00 PM	7:43:00 AM			

Sample Notes:

Summary for EMSL Kit 135663 Average Radon Result: **0.1 pCi/L**

Samples for EMSL Kit 135710

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
230011	Health Room	0.3	1/29/2016	2/1/2016	65	40	Customer
381600881-0003			1:06:00 PM	7:44:00 AM			

Sample Notes:

229907	Health Room	0.4	1/29/2016	2/1/2016	65	40	Customer
381600881-0004			1:07:00 PM	7:45:00 AM			

Sample Notes:

Summary for EMSL Kit 135710 Average Radon Result: **0.4 pCi/L**

Samples for EMSL Kit 135676

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
228971	Classroom 2	0.4	1/29/2016	2/1/2016	65	40	Customer
381600881-0005			1:08:00 PM	7:46:00 AM			

Sample Notes:

228950	Classroom 2	0.4	1/29/2016	2/1/2016	65	40	Customer
381600881-0006			1:09:00 PM	7:47:00 AM			

Sample Notes:

Summary for EMSL Kit 135676 Average Radon Result: **0.4 pCi/L**

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077
 Phone/Fax: (800) 220-3675 / (856) 786-0327
<http://www.EMSL.com> cinnaminsonradonlab@emsl.com

EMSL Order: 381600881
 CustomerID: PGCS62
 CustomerPO: 608048
 ProjectID:

Attn: **Karen Bowlding**
Prince George's County School
13300 Old Marlboro Pike
Upper Marlboro, MD 20772

Phone: (301) 952-6559
 Fax: (301) 952-0346
 Received: 02/02/16 1:49 PM
 Analysis Date: 2/4/2016
 Collected: 1/29/2016

Project: **Mattaponi ES**

Test Site: **Prince George's County School**
Mattaponi ES
Upper Marlboro, MD 20772

Test Report: Radon in Air Test Results**Samples for EMSL Kit 135679**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
230053	Classroom 4	0.6	1/29/2016	2/1/2016	65	40	Customer
381600881-0007			1:10:00 PM	7:48:00 AM			

Sample Notes:

229894	Classroom 4	0.6	1/29/2016	2/1/2016	65	40	Customer
381600881-0008			1:11:00 PM	7:49:00 AM			

Sample Notes:

Summary for EMSL Kit 135679 **Average Radon Result: 0.6 pCi/L**

Samples for EMSL Kit 135684

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
230160	Classroom 6	0.8	1/29/2016	2/1/2016	65	40	Customer
381600881-0009			1:12:00 PM	7:50:00 AM			

Sample Notes:

230037	Classroom 6	0.7	1/29/2016	2/1/2016	65	40	Customer
381600881-0010			1:13:00 PM	7:51:00 AM			

Sample Notes:

Summary for EMSL Kit 135684 **Average Radon Result: 0.8 pCi/L**

Samples for EMSL Kit 135669

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
229344	Classroom 10	1.7	1/29/2016	2/1/2016	65	40	Customer
381600881-0011			1:14:00 PM	7:52:00 AM			

Sample Notes:

229260	Classroom 10	1.7	1/29/2016	2/1/2016	65	40	Customer
381600881-0012			1:15:00 PM	7:53:00 AM			

Sample Notes:

Summary for EMSL Kit 135669 **Average Radon Result: 1.7 pCi/L**

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077
 Phone/Fax: (800) 220-3675 / (856) 786-0327
<http://www.EMSL.com> cinnaminsonradonlab@emsl.com

EMSL Order:	381600881
CustomerID:	PGCS62
CustomerPO:	608048
ProjectID:	

Attn: **Karen Bowlding**
Prince George's County School
13300 Old Marlboro Pike
Upper Marlboro, MD 20772

Phone: (301) 952-6559
 Fax: (301) 952-0346
 Received: 02/02/16 1:49 PM
 Analysis Date: 2/4/2016
 Collected: 1/29/2016

Project: **Mattaponi ES**

Test Site: **Prince George's County School**
Mattaponi ES
Upper Marlboro, MD 20772

Test Report: Radon in Air Test Results**Samples for EMSL Kit 135657**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
229481	Media Center	0.6	1/29/2016	2/1/2016	65	40	Customer
381600881-0013			1:16:00 PM	7:54:00 AM			

Sample Notes:

229334	Media Center	0.5	1/29/2016	2/1/2016	65	40	Customer
381600881-0014			1:17:00 PM	7:55:00 AM			

Sample Notes:

Summary for EMSL Kit 135657 **Average Radon Result: 0.6 pCi/L**

Samples for EMSL Kit 135666

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
229450	Classroom 19	0.8	1/29/2016	2/1/2016	65	40	Customer
381600881-0015			1:18:00 PM	7:56:00 AM			

Sample Notes:

229397	Classroom 19	0.6	1/29/2016	2/1/2016	65	40	Customer
381600881-0016			1:19:00 PM	7:57:00 AM			

Sample Notes:

Summary for EMSL Kit 135666 **Average Radon Result: 0.7 pCi/L**

Samples for EMSL Kit 135664

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
229348	Classroom 23	0.4	1/29/2016	2/1/2016	65	40	Customer
381600881-0017			1:20:00 PM	7:58:00 AM			

Sample Notes:

228964	Classroom 23	0.4	1/29/2016	2/1/2016	65	40	Customer
381600881-0018			1:21:00 PM	7:59:00 AM			

Sample Notes:

Summary for EMSL Kit 135664 **Average Radon Result: 0.4 pCi/L**

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077
 Phone/Fax: (800) 220-3675 / (856) 786-0327
<http://www.EMSL.com> cinnaminsonradonlab@emsl.com

EMSL Order:	381600881
CustomerID:	PGCS62
CustomerPO:	608048
ProjectID:	

Attn: **Karen Bowlding**
Prince George's County School
13300 Old Marlboro Pike
Upper Marlboro, MD 20772

Phone: (301) 952-6559
 Fax: (301) 952-0346
 Received: 02/02/16 1:49 PM
 Analysis Date: 2/4/2016
 Collected: 1/29/2016

Project: **Mattaponi ES**

Test Site: **Prince George's County School**
Mattaponi ES
Upper Marlboro, MD 20772

Test Report: Radon in Air Test Results**Samples for EMSL Kit 135659**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
229416	Classroom 22	0.3	1/29/2016	2/1/2016	65	40	Customer
381600881-0019			1:22:00 PM	8:00:00 AM			

Sample Notes:

229384	Classroom 22	0.2	1/29/2016	2/1/2016	65	40	Customer
381600881-0020			1:23:00 PM	8:01:00 AM			

Sample Notes:

Summary for EMSL Kit 135659 **Average Radon Result: 0.3 pCi/L**

Samples for EMSL Kit 135680

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
230061	E.I.A Office	0.5	1/29/2016	2/1/2016	65	40	Customer
381600881-0021			1:24:00 PM	8:02:00 AM			

Sample Notes:

230045	E.I.A Office	0.8	1/29/2016	2/1/2016	65	40	Customer
381600881-0022			1:25:00 PM	8:03:00 AM			

Sample Notes:

Summary for EMSL Kit 135680 **Average Radon Result: 0.6 pCi/L**

Samples for EMSL Kit 135658

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
229394	Classroom 18	0.7	1/29/2016	2/1/2016	65	40	Customer
381600881-0023			1:26:00 PM	8:04:00 AM			

Sample Notes:

229383	Classroom 18	0.8	1/29/2016	2/1/2016	65	40	Customer
381600881-0024			1:27:00 PM	8:05:00 AM			

Sample Notes:

Summary for EMSL Kit 135658 **Average Radon Result: 0.8 pCi/L**

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (800) 220-3675 / (856) 786-0327

<http://www.EMSL.com>cinnaminsonradonlab@emsl.com

EMSL Order: 381600881

CustomerID: PGCS62

CustomerPO: 608048

ProjectID:

Attn: **Karen Bowlding**
Prince George's County School
13300 Old Marlboro Pike
Upper Marlboro, MD 20772

Phone: (301) 952-6559
 Fax: (301) 952-0346
 Received: 02/02/16 1:49 PM
 Analysis Date: 2/4/2016
 Collected: 1/29/2016

Project: **Mattaponi ES**

Test Site: **Prince George's County School**
Mattaponi ES
Upper Marlboro, MD 20772

Test Report: Radon in Air Test Results**Samples for EMSL Kit 135670**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
229358	TV Studio 10A	0.2	1/29/2016	2/1/2016	65	40	Customer
381600881-0025			1:28:00 PM	8:06:00 AM			

Sample Notes:

229291	TV Studio 10A	0.1	1/29/2016	2/1/2016	65	40	Customer
381600881-0026			1:29:00 PM	8:07:00 AM			

Sample Notes:**Summary for EMSL Kit 135670 Average Radon Result: 0.2 pCi/L****Samples for EMSL Kit 135660**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
229339	Classroom 13	0.2	1/29/2016	2/1/2016	65	40	Customer
381600881-0027			1:30:00 PM	8:08:00 AM			

Sample Notes:

229336	Classroom 13	0.2	1/29/2016	2/1/2016	65	40	Customer
381600881-0028			1:31:00 PM	8:09:00 AM			

Sample Notes:**Summary for EMSL Kit 135660 Average Radon Result: 0.2 pCi/L****Samples for EMSL Kit 135667**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
229372	Classroom 16	0.5	1/29/2016	2/1/2016	65	40	Customer
381600881-0029			1:32:00 PM	8:10:00 AM			

Sample Notes:

229321	Classroom 16	0.8	1/29/2016	2/1/2016	65	40	Customer
381600881-0030			1:33:00 PM	8:11:00 AM			

Sample Notes:**Summary for EMSL Kit 135667 Average Radon Result: 0.6 pCi/L**

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077
 Phone/Fax: (800) 220-3675 / (856) 786-0327
<http://www.EMSL.com> cinnaminsonradonlab@emsl.com

EMSL Order: 381600881
 CustomerID: PGCS62
 CustomerPO: 608048
 ProjectID:

Attn: **Karen Bowlding**
Prince George's County School
13300 Old Marlboro Pike
Upper Marlboro, MD 20772

Phone: (301) 952-6559
 Fax: (301) 952-0346
 Received: 02/02/16 1:49 PM
 Analysis Date: 2/4/2016
 Collected: 1/29/2016

Project: **Mattaponi ES**

Test Site: **Prince George's County School**
Mattaponi ES
Upper Marlboro, MD 20772

Test Report: Radon in Air Test Results**Samples for EMSL Kit 135671**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
229460	Classroom 12	0.3	1/29/2016	2/1/2016	65	40	Customer
381600881-0031			1:34:00 PM	8:12:00 AM			

Sample Notes:

228969	Classroom 12	0.2	1/29/2016	2/1/2016	65	40	Customer
381600881-0032			1:35:00 PM	8:13:00 AM			

Sample Notes:

Summary for EMSL Kit 135671 **Average Radon Result: 0.3 pCi/L**

Samples for EMSL Kit 135681

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
230055	Classroom 8	0.1	1/29/2016	2/1/2016	65	40	Customer
381600881-0033			1:36:00 PM	8:14:00 AM			

Sample Notes:

229885	Classroom 8	0.1	1/29/2016	2/1/2016	65	40	Customer
381600881-0034			1:37:00 PM	8:15:00 AM			

Sample Notes:

Summary for EMSL Kit 135681 **Average Radon Result: 0.1 pCi/L**

Samples for EMSL Kit 135683

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
230021	Base LP Office	0.1	1/29/2016	2/1/2016	65	40	Customer
381600881-0035			1:38:00 PM	8:16:00 AM			

Sample Notes:

229961	Base LP Office	0.2	1/29/2016	2/1/2016	65	40	Customer
381600881-0036			1:39:00 PM	8:17:00 AM			

Sample Notes:

Summary for EMSL Kit 135683 **Average Radon Result: 0.2 pCi/L**

