Soil and Land Use Technology, Inc.
1818 New York Ave. NE, Ste 231, Washington, DC 20002
Telephone: (301) 595-3783
www.salutinc.com

January 5, 2021

Prince George's County Public Schools
Environmental Safety Office
13306 Old Marlboro Pike
Upper Marlboro, MD 20772

Attention: Alex Baylor
alex.baylor@pgcps.org

Subject: Indoor Air Quality Survey
Hillcrest Heights ES
4305 22nd Place
Hillcrest Heights, MD 20748

Mr. Baylor:

On November 19, 2020, a Soil and Land Use Technology, Inc. (SaLUT) Industrial Hygienist conducted an indoor air quality (IAQ) evaluation at Hillcrest Heights Elementary School, a property maintained by Prince George's County Public Schools (PGCPS) located at 4305 22nd Place, Hillcrest Heights, MD 20748. The inspection was performed in accordance with PGCPS contract number IFB 022-19.

Methodology

The IAQ evaluation conducted by SaLUT included a visual assessment, IAQ instrumentation screening, and a collection of interior air samples for mold in representative locations throughout the building. Additionally, one building exterior environmental air sample was taken for comparison.

Air-borne fungal spore samples were collected on *Air-O-Cell* cassettes using a Buck BioAire calibrated pump. The air samples were taken between three and five feet from the ground. In tandem with collecting mold samples, real-time readings for carbon dioxide, carbon monoxide, temperature and relative humidity were collected using a Fluke 975 Air Meter in representative areas within the facility.

The fungal spore air samples were delivered to EMSL Analytical, Inc. of Beltsville, Maryland for analysis. Fungal spores and particulates in air samples were analyzed by Optical Microscopy (methods EMSL 05-TP-003 and ASTM D7391). The sample chain-of-custody and laboratory reports are attached.

Observations

The table below summarizes the main observations from the IAQ survey at Hillcrest Heights Elementary School , visited on November 19, 2020.

Table 1-Observations

Location	Summary of Observations 11-19-2020
Next to Primary Classrooms B-23 & B-24	2'x4' ceiling tiles; No visual signs of microbial growth; Mild odor; One stained ceiling tile; No visible dust on floor/other furniture surfaces; No visible dust around ventilator; Central AC.
Next to Teacher Planning D-43	2'x4' ceiling tiles and 9"x9" tile floor; No visual signs of microbial growth, and no odor; No visible dust on floor/other furniture surfaces; No visible dust around ventilator; Central AC.
Adjacent to the Principal's Office	2'x4' ceiling tiles; No visual signs of microbial growth, and no odor; No visible dust on floor/other furniture surfaces; Unit ventilator system and window AC unit.
Next to the Main Office	2'x4' ceiling tiles and 12"x 12" tile floor; No visual signs of microbial growth, and no odor; No visible dust on floor/other furniture surfaces; No visible dust around ventilator; Central AC.
Gymnasium Basketball Court	2'x4' ceiling tiles and 9"x9"/1'x1' tile floor; No visual signs of microbial growth, and no odor; No visible dust on floor/other furniture surfaces; No visible dust around ventilator; Central AC.

Measurements of Indoor Environmental Quality Parameters

Table 2 depicts a summary of average measurements of comfort.

Temperature

The American Society of Heating, Refrigerating and Air-Conditioning Engineers (ASHRAE) have published recommendations for year round acceptable temperatures in Standard 55-2010 *Thermal Environmental Conditions for Human Occupancy*. The winter comfort range is 20 to 24°C (68 to 75°F) and 23 to 26°C (73 to 79°F) is the summer comfort range. The temperature readings were within the ASHRAE recommended ranges in the representative spaces.

Relative Humidity (RH)

RH is a key factor for mold growth. Mold has the potential of growing on suitable surfaces with humidity levels above 60%. ASHRAE Standard 62.1-2010 *Ventilation for Acceptable Indoor Air Quality* recommends a maximum indoor RH of 65% to preclude the likelihood of condensation on cool surfaces encouraging mold growth. The RH readings were within the ASHRAE recommended ranges in the representative areas.

Carbon Dioxide (CO_2)

Under conditions of maximum occupancy, ASHRAE Standard 62.1-2010, Appendix C, infers that the acceptable CO_2 upper limit is the prevailing outdoor CO_2 concentration plus 700 parts per million (ppm). On the day of the space evaluation, the outdoor (building exterior) CO_2 concentration was approximately 434 ppm therefore indoor concentrations should not exceed approximately 1,134 ppm (700 + 434). The maximum average interior CO_2 concentration detected was 539 ppm in the area adjacent to the Principal's Office, a range within the ASHRAE recommendations, per Table 2 below.

Carbon Monoxide (CO)

CO is a colorless and odorless gas that is produced by the incomplete combustion of carbon containing fuels. Oil, gasoline, diesel fuels, wood, coke, and coal are major sources of CO. All registered CO concentrations were below the EPA National Ambient Air Quality Standard (NAAQS) of 9 ppm, per Table 2 below.

Table 2: Hillcrest Heights Elementary School, Instrumental Screening Levels November 19, 2020 (7:30AM-9:30 AM)

Sample Location	Temp °F	RH%	CO ppm	CO_2 ppm
Standards	**ASHRAE 68 to 75°F***	**ASHRAE <65%**	**NAAQS 9**	**ASHRAE 1,134**
Next to the Primary Classroom B-23 & B-24	64.4	30.8	0	511
Next to Teachers Planning D-43	72.5	22.5	0	477
Adjacent to the Principal's Office	69.8	28.8	0	539
Next to the Main Office	70.7	27.5	0	458
Next to the Gymnasium Basketball Court	70.7	26.5	0	483
Outside Exterior EV Sample	52.7	35.6	0	434

PM – Particulate Matter size
°F – Degrees Fahrenheit
CO – Carbon Monoxide
ppm – parts per million
µg/m^3 – micrograms per cubic meter
RH% - % Relative Humidity
CO_2 – Carbon Dioxide
* - Winter Comfort Range

Mold-in-Air Samples

There are no definitive regulations or standardized guidelines for addressing airborne mold in an indoor setting. If building systems (ventilation, envelope) are functioning properly, the indoor population profile should mimic what is encountered outdoors and the concentrations should be below the outdoor (building exterior) environmental sample levels.

Tables 3 summarizes airborne mold spore sampling results and locations. On November 19, 2020, total mold counts in representative samples (spore count/m^3 of air) in all the areas inspected were lower than the outdoor concentrations. Laboratory analysis follows this report (see attachment).

Table 3: Hillcrest Heights Elementary School
Measurements of Mold-in-Air Samples
November 19, 2020 (7:30 AM-9:30 AM)

Spore Types	Next to Primary Classroom B-23 & B-24	Next to Teachers Planning D-43	Adjacent to the Principal's Office	Next to the Main Office
Alternaria (Ulocladium)	-	-	-	-
Ascospores	40	40	40	-
Aspergillus/Penicillium	-	2,300	410	100
Basidiospores	450	200	450	300
Bipolaris++	-	-	-	-
Chaetomium	-	-	-	-
Cladosporium	100	-	40	80
Curvularia	-	-	-	-
Epicoccum	-	10*	-	-
Fusarium	-	-	-	-
Ganoderma	-	-	-	-
Myxomycetes++	40	10*	40	80
Pithomyces++	-	-	-	-
Rust	-	-	80	-
Scopulariopsis/Microascus	-	-	-	-
Stachybotrys/Memnoniella	-	-	-	-
Unidentifiable Spores	-	-	-	-
Zygomycetes	-	-	-	-
Nigrospora	-	-	-	-
Hyphal Fragment	-	-	80	-
Insect Fragment	40	-	80	10*
Pollen	-	-	-	-
Total Fungi	**630**	**2,560**	**1,060**	**560**

* Spore Counts per cubic meter of air (Counts/m^3).
++Includes other spores with similar morphology.

Table 3: Hillcrest Heights Elementary School
Measurements of Mold-in-Air Samples continued
November 19, 2020 (7:30 AM-9:30 AM)

Spore Types	Next to the Gymnasium Basketball Court	Outside Exterior EV Sample	Field Blank
Alternaria (Ulocladium)	-	-	-
Ascospores	-	40	-
Aspergillus/Penicillium	490	80	-
Basidiospores	200	1,600	-
Bipolaris++	-	-	-
Chaetomium	-	-	-
Cladosporium	40	200	-
Curvularia	-	-	-
Epicoccum	-	-	-
Fusarium	-	-	-
Ganoderma	-	-	-
Myxomycetes++	40	30*	-
Pithomyces++	-	10*	-
Rust	-	40	-
Scopulariopsis/Microascus	-	-	-
Stachybotrys/Memnoniella	-	-	-
Unidentifiable Spores	-	-	-
Zygomycetes	-	-	-
Nigrospora	-	-	-
Hyphal Fragment	100	80	-
Insect Fragment	10*	10*	-
Pollen	-	-	-
Total Fungi	**770**	**2,000**	**No Trace**

*Spore Counts per cubic meter of air (Counts/m^3).
++Includes other spores with similar morphology.

Findings and Conclusions

The comfort parameters (i.e., temperature, RH, CO_2, and CO levels) in the representative areas conform to ASHRAE and/or NAAQS guidelines. On November 19, 2020, total mold counts in representative area samples (spore count/m^3 of air) in all the areas inspected were lower than the outdoor concentrations, indicating no amplified mold growth.

Thank you for the opportunity to provide industrial hygiene services for PGCPS. If you have any questions, please contact me at 301.595.3783.

Sincerely,



Chaminda Jayatilake, PE, CIH, CSP, CHMM
Certified Industrial Hygienist
Soil and Land Use Technology Inc. (SaLUT)

Attachment

Attachment - Mold Spore Sample Analytical Results and Chain-of-Custody Forms

Attachment

Mold Spore Sample Analytical Results and Chain-of-Custody Forms

EMSL Analytical, Inc.

10768 Baltimore Avenue Beltsville, MD 20705

Tel/Fax: (301) 937-5700 / (301) 937-5701

http://www.EMSL.com / beltsvillelab@emsl.com

EMSL Order: 192011523
Customer ID: SALU50
Customer PO:
Project ID:

Attention: Indika Jayatilake
SaLUT
1818 New York Avenue, NE
Suite 231
Washington, DC 20002
Project: Hillcrest Heights PG County IAQ

Phone: (301) 595-3783
Fax: (301) 595-3787
Collected Date: 11/19/2020
Received Date: 11/19/2020 12:58 PM
Analyzed Date: 11/23/2020

Test Report:Air-O-Cell(™) Analysis of Fungal Spores & Particulates by Optical Microscopy (Methods MICRO-SOP-201, ASTM D7391)

Lab Sample Number:	192011523-0001			192011523-0002			192011523-0003		
Client Sample ID:	S1			S2			S3		
Volume (L):	75			75			75		
Sample Location:	Next to the primary CR b-23&B-24			Adjacent to the Principal's office			Next to the main office		
Spore Types	**Raw Count**	**Count/M³**	**% of Total**	**Raw Count**	**Count/M³**	**% of Total**	**Raw Count**	**Count/M³**	**% of Total**
Alternaria (Ulocladium)	-	-	-	-	-	-	-	-	-
Ascospores	1	40	6.3	1	40	3.8	-	-	-
Aspergillus/Penicillium	-	-	-	10	410	38.7	3	100	17.9
Basidiospores	11	450	71.4	11	450	42.5	7	300	53.6
Bipolaris++	-	-	-	-	-	-	-	-	-
Chaetomium	-	-	-	-	-	-	-	-	-
Cladosporium	3	100	15.9	1	40	3.8	2	80	14.3
Curvularia	-	-	-	-	-	-	-	-	-
Epicoccum	-	-	-	-	-	-	-	-	-
Fusarium	-	-	-	-	-	-	-	-	-
Ganoderma	-	-	-	-	-	-	-	-	-
Myxomycetes++	1	40	6.3	1	40	3.8	2	80	14.3
Pithomyces++	-	-	-	-	-	-	-	-	-
Rust	-	-	-	2	80	7.5	-	-	-
Scopulariopsis/Microascus	-	-	-	-	-	-	-	-	-
Stachybotrys/Memnoniella	-	-	-	-	-	-	-	-	-
Unidentifiable Spores	-	-	-	-	-	-	-	-	-
Zygomycetes	-	-	-	-	-	-	-	-	-
Total Fungi	**16**	**630**	**100**	**26**	**1060**	**100**	**14**	**560**	**100**
Hyphal Fragment	-	-	-	2	80	-	-	-	-
Insect Fragment	1	40	-	2	80	-	1*	10*	-
Pollen	-	-	-	-	-	-	-	-	-
Analyt. Sensitivity 600x	-	41	-	-	41	-	-	41	-
Analyt. Sensitivity 300x	-	13*	-	-	13*	-	-	13*	-
Skin Fragments (1-4)	-	2	-	-	2	-	-	2	-
Fibrous Particulate (1-4)	-	1	-	-	1	-	-	1	-
Background (1-5)	-	1	-	-	1	-	-	1	-

++ Includes other spores with similar morphology; see EMSL's fungal glossary for each specific category.

Abubakar Barry, Microbiology Laboratory Manager
or other Approved Signatory

Initial report from: 11/24/2020 09:03 AM

For information on the fungi listed in this report, please visit the Resources section at www.emsl.com

EMSL Analytical, Inc.

10768 Baltimore Avenue Beltsville, MD 20705

Tel/Fax: (301) 937-5700 / (301) 937-5701

http://www.EMSL.com / beltsvillelab@emsl.com

EMSL Order: 192011523
Customer ID: SALU50
Customer PO:
Project ID:

Attention: Indika Jayatilake
SaLUT
1818 New York Avenue, NE
Suite 231
Washington, DC 20002
Project: Hillcrest Heights PG County IAQ

Phone: (301) 595-3783
Fax: (301) 595-3787
Collected Date: 11/19/2020
Received Date: 11/19/2020 12:58 PM
Analyzed Date: 11/23/2020

Test Report:Air-O-Cell(™) Analysis of Fungal Spores & Particulates by Optical Microscopy (Methods MICRO-SOP-201, ASTM D7391)

Lab Sample Number:	192011523-0004			192011523-0005			192011523-0006		
Client Sample ID:	S4			S5			S6		
Volume (L):	75			75			75		
Sample Location:	Next to the teacher planing D-43			Gymnasium Basket ball court			Ambient		
Spore Types	**Raw Count**	**Count/M³**	**% of Total**	**Raw Count**	**Count/M³**	**% of Total**	**Raw Count**	**Count/M³**	**% of Total**
Alternaria (Ulocladium)	-	-	-	-	-	-	-	-	-
Ascospores	1	40	1.6	-	-	-	1	40	2
Aspergillus/Penicillium	55	2300	89.8	12	490	63.6	2	80	4
Basidiospores	6	200	7.8	5	200	26	38	1600	80
Bipolaris++	-	-	-	-	-	-	-	-	-
Chaetomium	-	-	-	-	-	-	-	-	-
Cladosporium	-	-	-	1	40	5.2	5	200	10
Curvularia	-	-	-	-	-	-	-	-	-
Epicoccum	1*	10*	0.4	-	-	-	-	-	-
Fusarium	-	-	-	-	-	-	-	-	-
Ganoderma	-	-	-	-	-	-	-	-	-
Myxomycetes++	1*	10*	0.4	1	40	5.2	2*	30*	1.5
Pithomyces++	-	-	-	-	-	-	1*	10*	0.5
Rust	-	-	-	-	-	-	1	40	2
Scopulariopsis/Microascus	-	-	-	-	-	-	-	-	-
Stachybotrys/Memnoniella	-	-	-	-	-	-	-	-	-
Unidentifiable Spores	-	-	-	-	-	-	-	-	-
Zygomycetes	-	-	-	-	-	-	-	-	-
Total Fungi	**64**	**2560**	**100**	**19**	**770**	**100**	**50**	**2000**	**100**
Hyphal Fragment	-	-	-	3	100	-	2	80	-
Insect Fragment	-	-	-	1*	10*	-	1*	10*	-
Pollen	-	-	-	-	-	-	-	-	-
Analyt. Sensitivity 600x	-	41	-	-	41	-	-	41	-
Analyt. Sensitivity 300x	-	13*	-	-	13*	-	-	13*	-
Skin Fragments (1-4)	-	2	-	-	2	-	-	1	-
Fibrous Particulate (1-4)	-	1	-	-	1	-	-	1	-
Background (1-5)	-	1	-	-	1	-	-	1	-

++ Includes other spores with similar morphology; see EMSL's fungal glossary for each specific category.

Abubakar Barry, Microbiology Laboratory Manager or other Approved Signatory

Initial report from: 11/24/2020 09:03 AM

For information on the fungi listed in this report, please visit the Resources section at www.emsl.com

EMSL Analytical, Inc.

10768 Baltimore Avenue Beltsville, MD 20705

Tel/Fax: (301) 937-5700 / (301) 937-5701

http://www.EMSL.com / beltsvillelab@emsl.com

EMSL Order: 192011523
Customer ID: SALU50
Customer PO:
Project ID:

Attention: Indika Jayatilake
SaLUT
1818 New York Avenue, NE
Suite 231
Washington, DC 20002
Project: Hillcrest Heights PG County IAQ

Phone: (301) 595-3783
Fax: (301) 595-3787
Collected Date: 11/19/2020
Received Date: 11/19/2020 12:58 PM
Analyzed Date: 11/23/2020

Test Report:Air-O-Cell(™) Analysis of Fungal Spores & Particulates by Optical Microscopy (Methods MICRO-SOP-201, ASTM D7391)

Lab Sample Number:	**192011523-0007**		
Client Sample ID:	**S7**		
Volume (L):			
Sample Location:	**Field blank**		
Spore Types	**Raw Count**	**Count/M³**	**% of Total**
Alternaria (Ulocladium)	-	-	-
Ascospores	-	-	-
Aspergillus/Penicillium	-	-	-
Basidiospores	-	-	-
Bipolaris++	-	-	-
Chaetomium	-	-	-
Cladosporium	-	-	-
Curvularia	-	-	-
Epicoccum	-	-	-
Fusarium	-	-	-
Ganoderma	-	-	-
Myxomycetes++	-	-	-
Pithomyces++	-	-	-
Rust	-	-	-
Scopulariopsis/Microascus	-	-	-
Stachybotrys/Memnoniella	-	-	-
Unidentifiable Spores	-	-	-
Zygomycetes	-	-	-
Total Fungi	**-**	**No Trace**	**-**
Hyphal Fragment	-	-	-
Insect Fragment	-	-	-
Pollen	-	-	-
Analyt. Sensitivity 600x	-	0	-
Analyt. Sensitivity 300x	-	0*	-
Skin Fragments (1-4)	-	-	-
Fibrous Particulate (1-4)	-	-	-
Background (1-5)	-	-	-

++ Includes other spores with similar morphology; see EMSL's fungal glossary for each specific category.

Abubakar Barry, Microbiology Laboratory Manager
or other Approved Signatory

Initial report from: 11/24/2020 09:03 AM

For information on the fungi listed in this report, please visit the Resources section at www.emsl.com

OrderID: 192011523

Microbiology Chain of Custody

EMSL Order Number *(Lab Use Only)*: 192011523

EMSL ANALYTICAL, INC.
200 ROUTE 130 NORTH
CINNAMINSON, NJ 08077
PHONE: (800) 220-3675
FAX:(856) 786-0262

Company Name: Salut Inc	**EMSL-Bill to:** ☐ Same ☐ Different If Bill to is Different note instructions in Comments
Street: 1818 New York Ave NE Suite 231	*Third Party Billing requires written authorization from third party.*
City: Washington **State/Province:** DC	**Zip/Postal Code:** **Country:**
Report To (Name): Indika Jayatilake	**Telephone #:**
Email Address: ijayatilake@salutinc.com	**Fax #:** **Purchase Order:**
Project Name/Number: Hillcrest Heights PG County IAQ	**Please Provide Results:** ☐ Fax ☐ Email

U.S. State Samples Taken: PG County **Project Zip Code:** 20748 **Connecticut Samples:** ☐ Commercial ☐ Residential

Sterile, Sodium Thiosulfate Preserved Bottle Used: ☐ **Biocide Used in Source (specify):** ☐

Public Water Supply Samples: ☐ **Note: All results may automatically be reported to DOH if required by state.**

Turnaround Time (TAT) Options - Please Check

☐ 3 Hour	☐ 6 Hour	☐ 24 Hour	☐ 48 Hour	■ 72 Hour	☐ 96 Hour	☐ 1 Week	☐ 2 Week

Microbiology Test Codes

M001 Air-O-Cell
M174 MoldSnap
M030 Micro 5
M032 Allergenco-D
M041 Fungal Direct Examination
M169 Pollen ID & Enumeration
M280 Dust Characterization Level-1
M281 Dust Characterization Level-2
M005 Viable Fungi- Air Samples (Genus ID & Count)
M006 Viable Fungi- Air Samples (Includes *Penicillium, Aspergillus, Cladosporium, Stachybotrys* Species ID & Count)
M007 Culturable fungi - Surface Samples (Genus ID & Count)
M008 Culturable fungi - Surface Samples (Includes *Penicillium, Aspergillus, Cladosporium, Stachybotrys* Species ID & Count)
M009 Bacteria Culture Gram Stain & Count
M010 Bacteria Count & ID - 3 Most Prominent
M011 Bacteria Count & ID - 5 Most Prominent

M012 *Pseudomonas aeruginosa* (P/A***)
M024 *Pseudomonas aeruginosa* (MFT*)
M015 Heterotrophic Plate Count
M017 Total Coliform & *E. coli* (Colilert P/A***)
M018 Total Coliform & *E. coli* (MFT*)
M114 Total Coliform & *E. coli* Enumeration (Colilert MPN**)
M019 Fecal Coliform (MFT*)
M020 Fecal *Streptococcus* (MFT*)
M029 *Enterococci* (MFT*)
M129 *Enterococci* (Enterolert P/A***)
M180 Real Time qPCR-ERMI 36 Panel
M025 Sewage Screen –Water (MFT*)

M115 Sewage Screen - Water (P/A***)
M116 Sewage Screen - Water (MPN**)
M117 Sewage Screen - Swab (P/A***)
M013 Sewage Screen - Swab (MFT*)
M133 *Methicillin-resistant Staph. aureus* (MRSA)
M031 Rapid-growing non-TB *Mycobacteria* Detection & Enumeration
M014 Endotoxin Analysis
M044 Group Allergen (Cat, Dog, Cockroach, Dust Mite)
Other See Analytical Price Guide
***Legionella* Analysis** Please use EMSL *Legionella* COC

*MFT= Membrane Filtration Technique
**MPN= Most Probable Number
***P/A= Presence/Absence

Name of Sampler: Shenal Dias **Signature of Sampler:**

Sample #	Sample Location/Description	Sample Type	Potable/ NonPotable (Only for Waters)	Test Code	Volume/ Area	Date/Time Collected	Temperature (°C) (Lab Use Only)
Example A1	Kitchen Sink/Tap	Water	☒ P ☐ NP	M017	100 mL	9/1/13 4:00 PM	
S1	Next to the primary CR b-23&B-24	Air	☐ P ☐ NP	M001	75L	11/19/2020	
S2	adjacent to the Principal's office	Air	☐ P ☐ NP	M001	75L	11/19/2020	
S3	Next to the main office	Air	☐ P ☐ NP	M001	75L	11/19/2020	
S4	Next to the teacher planing D-43	Air	☐ P ☐ NP	M001	75L	11/19/2020	
S5	Gymnasium Basket ball court	Air	☐ P ☐ NP	M001	75L	11/19/2020	

Client Sample # (s): - **Total # of Samples:** 07 **Samples Received Chilled?** Yes / No (Lab Use Only)

Relinquished (Client): **Date:** **Time:**

Received (Lab): **Date:** **Time:**

Comments/Special Instructions:

RECEIVED
EMSL ANALYTICAL, INC.
BELTSVILLE, MD
2020 NOV 19 P 12:58

Controlled Document – COC-34 Micro R8 11/14/2017

OrderID: 192011523

EMSL ANALYTICAL, INC.
LABORATORY • PRODUCTS • TRAINING

Microbiology Chain of Custody

EMSL Order Number *(Lab Use Only)*: 192011523

EMSL ANALYTICAL, INC.
200 ROUTE 130 NORTH
CINNAMINSON, NJ 08077
PHONE: (800) 220-3675
FAX:(856) 786-0262

Additional pages of the chain of custody are only necessary if needed for additional sample information.

Sample #	Sample Location/Description	Sample Type	Potable/ NonPotable (Only for Waters)	Test Code	Volume/ Area	Date/Time Collected	Temperature (°C) (Lab Use Only)
S6	Ambient	Air	☐P ☐NP	M001	75L	11/19/2020	
S7	Field blank	Air	☐P ☐NP	M001	75L	11/19/2020	
			☐P ☐NP				
			☐P ☐NP				
			☐P ☐NP				
			☐P ☐NP				
			☐P ☐NP				
			☐P ☐NP				
			☐P ☐NP				
			☐P ☐NP				
			☐P ☐NP				
			☐P ☐NP				
			☐P ☐NP				
			☐P ☐NP				
			☐P ☐NP				
			☐P ☐NP				
			☐P ☐NP				
			☐P ☐NP				
			☐P ☐NP				
			☐P ☐NP				
			☐P ☐NP				
			☐P ☐NP				

Comments/Special Instructions:

Page ______ of ______