



# EMSL Analytical, Inc.

200 Route 130 North, Cinnaminson, NJ 08077  
Phone/Fax: (800) 220-3675 / (856) 786-0327  
<http://www.EMSL.com> [cinnaminsonradonlab@emsl.com](mailto:cinnaminsonradonlab@emsl.com)

EMSL Order: 382306942  
CustomerID: GLBW42  
CustomerPO:  
ProjectID:

Attn: **Channa Bambaradeniya**  
**Global Inc.**  
**1818 New York Avenue NE**  
**Suite 222**  
**Washington, DC 20002**

Phone: (202) 832-1433  
Fax:  
Received: 11/17/2023 08:56 AM  
Analysis Date: 11/17/2023  
Collected: 11/10/2023

Project: **Gwynn Park HS / 13800 Brandywine Rd**

Test Site: **Gwynn Park HS**  
**13800 Brandywine Rd**  
**Brandywine, MD 20613**

## Test Report: Radon in Air Test Results

### Samples for EMSL Kit 309313

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
550532	148 Cosmology	0.1	11/10/2023	11/13/2023	75	35	Customer
382306942-0001			7:48:00 AM	7:42:00 AM			

Sample Notes:

### Samples for EMSL Kit 309285

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
550551	134	0.1	11/10/2023	11/13/2023	75	35	Customer
382306942-0002			7:52:00 AM	7:45:00 AM			

Sample Notes:

550421	134	-0.1	11/10/2023	11/13/2023	75	35	Blank
382306942-0003			7:52:00 AM	7:45:00 AM			

Sample Notes:

### Samples for EMSL Kit 308453

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
550348	136	-0.2	11/10/2023	11/13/2023	75	35	Customer
382306942-0004			7:54:00 AM	7:40:00 AM			

Sample Notes:

### Samples for EMSL Kit 309320

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
550871	147 Office	0.2	11/10/2023	11/13/2023	75	35	Customer
382306942-0005			7:57:00 AM	7:38:00 AM			

Sample Notes:



# EMSL Analytical, Inc.

200 Route 130 North, Cinnaminson, NJ 08077  
Phone/Fax: (800) 220-3675 / (856) 786-0327  
<http://www.EMSL.com> [cinnaminsonradonlab@emsl.com](mailto:cinnaminsonradonlab@emsl.com)

EMSL Order: 382306942  
CustomerID: GLBW42  
CustomerPO:  
ProjectID:

Attn: **Channa Bambaradeniya**  
**Global Inc.**  
**1818 New York Avenue NE**  
**Suite 222**  
**Washington, DC 20002**

Phone: (202) 832-1433  
Fax:  
Received: 11/17/2023 08:56 AM  
Analysis Date: 11/17/2023  
Collected: 11/10/2023

Project: **Gwynn Park HS / 13800 Brandywine Rd**

Test Site: **Gwynn Park HS**  
**13800 Brandywine Rd**  
**Brandywine, MD 20613**

## Test Report: Radon in Air Test Results

### Samples for EMSL Kit 309318

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
550565	139	0.3	11/10/2023	11/13/2023	75	35	Customer
382306942-0006			7:59:00 AM	7:14:00 AM			

#### Sample Notes:

547771	139	0.3	11/10/2023	11/13/2023	75	35	Duplicate
382306942-0007			7:59:00 AM	7:14:00 AM			

#### Sample Notes:

**Duplicate RPD = 0%**

### Samples for EMSL Kit 309317

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
550548	147 A	0.1	11/10/2023	11/13/2023	75	35	Customer
382306942-0008			8:02:00 AM	7:36:00 AM			

#### Sample Notes:

### Samples for EMSL Kit 308477

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
550247	Cafeteria	0.1	11/10/2023	11/13/2023	75	35	Customer
382306942-0009			8:05:00 AM	7:31:00 AM			

#### Sample Notes:

### Samples for EMSL Kit 309329

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
550541	Kitchen	0.1	11/10/2023	11/13/2023	75	35	Customer
382306942-0010			8:08:00 AM	7:34:00 AM			

#### Sample Notes:

### Samples for EMSL Kit 309307

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
550531	Gym	0.5	11/10/2023	11/13/2023	75	35	Customer
382306942-0011			8:11:00 AM	7:28:00 AM			

#### Sample Notes:



# EMSL Analytical, Inc.

200 Route 130 North, Cinnaminson, NJ 08077  
Phone/Fax: (800) 220-3675 / (856) 786-0327  
<http://www.EMSL.com> [cinnaminsonradonlab@emsl.com](mailto:cinnaminsonradonlab@emsl.com)

EMSL Order: 382306942  
CustomerID: GLBW42  
CustomerPO:  
ProjectID:

Attn: **Channa Bambaradeniya**  
**Global Inc.**  
**1818 New York Avenue NE**  
**Suite 222**  
**Washington, DC 20002**

Phone: (202) 832-1433  
Fax:  
Received: 11/17/2023 08:56 AM  
Analysis Date: 11/17/2023  
Collected: 11/10/2023

Project: **Gwynn Park HS / 13800 Brandywine Rd**

Test Site: **Gwynn Park HS**  
**13800 Brandywine Rd**  
**Brandywine, MD 20613**

## Test Report: Radon in Air Test Results

### Samples for EMSL Kit 309297

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
550553	Custodian Office	0.1	11/10/2023	11/13/2023	75	35	Customer
382306942-0012			8:15:00 AM	7:26:00 AM			

Sample Notes:

### Samples for EMSL Kit 309306

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
550884	Boiler Room	0.3	11/10/2023	11/13/2023	75	35	Customer
382306942-0013			8:18:00 AM	7:24:00 AM			

Sample Notes:

### Samples for EMSL Kit 309327

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
551036	154	0.5	11/10/2023	11/13/2023	75	35	Customer
382306942-0014			8:24:00 AM	7:47:00 AM			

Sample Notes:

### Samples for EMSL Kit 308463

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
550334	155	0.6	11/10/2023	11/13/2023	75	35	Customer
382306942-0015			8:27:00 AM	7:49:00 AM			

Sample Notes:

### Samples for EMSL Kit 309326

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
550870	156	0.4	11/10/2023	11/13/2023	75	35	Customer
382306942-0016			8:29:00 AM	7:20:00 AM			

Sample Notes:



# EMSL Analytical, Inc.

200 Route 130 North, Cinnaminson, NJ 08077  
Phone/Fax: (800) 220-3675 / (856) 786-0327  
<http://www.EMSL.com> [cinnaminsonradonlab@emsl.com](mailto:cinnaminsonradonlab@emsl.com)

EMSL Order: 382306942  
CustomerID: GLBW42  
CustomerPO:  
ProjectID:

Attn: **Channa Bambaradeniya**  
**Global Inc.**  
**1818 New York Avenue NE**  
**Suite 222**  
**Washington, DC 20002**

Phone: (202) 832-1433  
Fax:  
Received: 11/17/2023 08:56 AM  
Analysis Date: 11/17/2023  
Collected: 11/10/2023

Project: **Gwynn Park HS / 13800 Brandywine Rd**

Test Site: **Gwynn Park HS**  
**13800 Brandywine Rd**  
**Brandywine, MD 20613**

## Test Report: Radon in Air Test Results

### Samples for EMSL Kit 309286

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
550575	158	0.5	11/10/2023	11/13/2023	75	35	Customer
382306942-0017			8:33:00 AM	7:51:00 AM			

#### Sample Notes:

### Samples for EMSL Kit 309300

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
550521	157	0.3	11/10/2023	11/13/2023	75	35	Customer
382306942-0018			8:35:00 AM	7:50:00 AM			

#### Sample Notes:

The radon test was performed using a liquid scintillation radon detector/s and counted on a liquid scintillation counter using approved EPA testing protocols for Radon in Air testing. The EPA recommends fixing your home if the average of two short-term tests taken in the lowest lived-in level of the home show radon levels that are equal to or greater than 4.0pCi/L. The EPA recommends retesting your home every two years.

Please contact EMSL Analytical, Inc. or your State Health Department for further information. All procedures used for generating this report are in complete accordance with the current EPA protocols for the analysis of Radon in Air.

### Report Note

Analyst(s)

Jeanel Zoll (18)

Dominic Gehret, Radiochemistry Laboratory Manager, NJ Radon Measurement Specialist MES 13910 or other approved signatory

In no event shall EMSL be liable for indirect, special, consequential, or incidental damages, including, but not limited to, damages for loss of profit or goodwill regardless of the negligence (either sole or concurrent) of EMSL and whether EMSL has been informed of the possibility of such damages, arising out of or in connection with EMSL's services thereunder or the delivery, use, reliance upon or interpretation of test results by client or any third party. We accept no legal responsibility for the purposes for which the client uses the test results. In no event shall EMSL be liable to a client or any third party, whether based upon theories of tort, contract or any other legal or equitable theory, in excess of the amount paid to EMSL by client thereunder. The test results meets all NELAC requirements unless otherwise specified.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ FL RB2034/R2687,IL RNL2008202,IN RTL00935,IA RNLAB10005,KS KS-LB-0005/KS-MS-0482,ME SPC202,MN RL-0005,NE 474/RMB-1083,NJ 03036/MEB92525/MES13910,NY 10872,OH RL39,OK D9952,PA 2573/3393/68-00367,RI RMB-108/RI00179,WV RL000220,NRSB-ARL6006,NRPP

Initial report from 11/20/2023 17:45:35

Please visit [www.radontestinglab.com](http://www.radontestinglab.com)